

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nHMP 14132405860

Name of Company: BOPCO, L.P. <u>260 737</u>		OPERATOR	<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Contact: Tony Savoie		
Facility Name: Remuda Basin Battery Unit #1		Telephone No. 575-887-7329		
		Facility Type: Exploration and Production		
Surface Owner: State of N.M.		Mineral Owner: State of N.M.	API No. 30-015-03691	

LOCATION OF RELEASE

Unit Letter J	Section 24	Township 23S	Range 29E	Feet from the 1980	North/South Line South	Feet from the 198	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	----------------

Latitude: N 32.288041 Longitude: W 103.936333

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 15 bbls	Volume Recovered: None
Source of Release: Produced water storage tank	Date and Hour of Occurrence: 4/27/14 at 10 a.m.	Date and Hour of Discovery: 4/27/14 at 10 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Tony Savoie	Date and Hour 11/26/12 at 10:22 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

RECEIVED
MAY 09 2014
NMOCD ARTESIA

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.

The produced water transfer pump failed to start due to blown fuses. The facility normally makes less than 100 bls of water per day. The water production for the day was three times the normal production; it is suspected that produced water was unloaded into the water storage tanks from an unknown source.

Describe Area Affected and Cleanup Action Taken.*

The spill impacted an area of approximately 900 sq.ft. inside the tank batteries earthen containment. There is a remediation underway at the facility dealing with an unauthorized release on the well pad and reserve pit. The affected area in the pasture will be remediated in accordance to the NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Tony Savoie</u>	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by Environmental Specialist: <u>[Signature]</u>	
Title: Waste Management and Remediation Specialist	Approval Date: <u>5/12/14</u>	Expiration Date: <u>NA</u>
E-mail Address: <u>tasavoie@basspet.com</u>	Conditions of Approval:	
Date: <u>5/8/14</u> Phone: <u>432-556-8730</u>	Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	
	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

6/12/14
28P-2296

