

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

| | |
|--------------------------------------|-----------------------------------|
| Name of Company Apache Corporation | Contact Natalie Gladden |
| Address PO Box 1849, Eunice NM 88231 | Telephone No. 575-390-4186 |
| Facility Name EBDU Sat #2 | Facility Type Production Facility |
| Surface Owner McNeil Ranch | Mineral Owner Federal |
| API No. 30-025-06548 | |

LOCATION OF RELEASE


| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| C | 12 | 21S | 37E | 990' | FNL | 1650' | FWL | Lea |

Latitude _____ Longitude _____

NATURE OF RELEASE

| | | |
|---|--|---|
| Type of Release Oil | Volume of Release 25 | Volume Recovered 20 |
| Source of Release Dump valve failure | Date and Hour of Occurrence 11/10/11 302pm | Date and Hour of Discovery 11/10/11 302pm |
| Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? Geoffrey Leking | HOBBS OCD |
| By Whom? Natalie Gladden | Date and Hour 11/10/11 401pm | FEB 13 2012 |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |
| If a Watercourse was Impacted, Describe Fully.* | RECEIVED DTW = 57' | |
| Describe Cause of Problem and Remedial Action Taken.* Dump valve failure causing oil to be released out of vent line. | | |
| Describe Area Affected and Cleanup Action Taken.* Contaminated soil will be excavated to below the allowable levels and site will be remediated according to the NMOCD Rules and Regulations for Spills. | | |

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | |
|--|---|-----------------------------------|
| Signature:  | OIL CONSERVATION DIVISION | |
| Printed Name: Natalie Gladden |  Approved by Environmental Specialist: Environmental Specialist | |
| Title: EHS Environmental Tech | Approval Date: 2/13/12 | Expiration Date: 4/13/12 |
| E-mail Address: natalie.gladden@apachecorp.com | Conditions of Approval: SUBMIT FINAL | Attached <input type="checkbox"/> |
| Date: 11/16/11 Phone: 575-390-4186 | c-141 BY 4/13/12 | 1RR-10-13-2973 |

* Attach Additional Sheets If Necessary

ogrid
770141027491
JUN 10 2014