

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

**HOBBS OCD**

Form C-141  
Revised October 10, 2003

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**JUN 30 2014**

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

RECEIVED

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company	Oxy Permian Ltd.	Contact	CJ Summers
Address	1017 W. Stanolind Rd, Hobbs, NM	Telephone No.	(575) 397-8216
Facility Name	MLMU #137	Facility Type	Gathering
Surface Owner	Kelly Myers	Mineral Owner	
		API No.	30-025-11036

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	6	24S	37E	660	North	626	West	Lea

Latitude N 32.25171° Longitude W 103.20744°

**NATURE OF RELEASE**



Type of Release	Produced water	Volume of Release	40 bbls	Volume Recovered	0 bbls
Source of Release	Injection line leak	Date and Hour of Occurrence	04/11/2013	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Geoffrey Leking-NMOCD; Jennifer Van Curen, James Amose-BLM		
By Whom?	Chancey Summers	Date and Hour	04/11/2013 @ 10:40 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
An injection line leak caused 40 bbls of produced water to leak onto the ground. 0 bbls were recovered via vacuum truck and the injection line was repaired.

Describe Area Affected and Cleanup Action Taken.\*  
The area affected is approximately 20' x 80'. An injection line leak caused 40 bbls of produced water to leak on the ground. 0 bbls were recovered via vacuum truck and the injection line was repaired. Remediation was completed in accordance with the remediation plan approved by Geoffrey Leking of NMOCD via email on 02/03/2014.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		<b>OIL CONSERVATION DIVISION</b>	
Printed Name:	Chancey Summers	Approved by District Supervisor:	
Title:	HES Specialist	Approval Date:	7-1-14
E-mail Address:	Chancey.Summers@oxy.com	Expiration Date:	
Date:	6-23-14	Conditions of Approval:	
Phone:	(575) 397-8216	Attached	<input type="checkbox"/>
			7-14-3133

\* Attach Additional Sheets If Necessary

09119 192463

**JUL 01 2014**