

HOBBS OCD

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

JUL 0 3

RECEIVED

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Chevron	Contact: Bradley Blevins
Address: 1616 West Bender	Telephone No.: (575) 391 - 1462 ext 86424
Facility Name: Brunson Argo SWD	Facility Type: tank battery

Surface Owner: C&V Properties, LLC	Mineral Owner:	API: 30-025-10137
------------------------------------	----------------	-------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	9	22S	37E					Lea

Latitude: N 32° 24' 28.96" Longitude: W 103° 9' 56.48"

NATURE OF RELEASE

Type of Release: produced water	Volume of Release: 47 bbls	Volume Recovered: 40 bbls
Source of Release: tank battery	Date and Hour of Occurrence: 5/2/14 @ am	Date and Hour of Discovery: 5/2/14 @ am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Geoff Leking	
By Whom? Bradley Blevins	Date and Hour: 5/2/14 @ 09:16	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	

Depth to Water. ~80 ft bgs

If a Watercourse was Impacted, Describe Fully.* Not Applicable

Describe Cause of Problem and Remedial Action Taken.* Approximately 47 bbls of produced water were released when the pump equipment failed at the battery causing the tank to run over releasing 47 barrels of produced water to the secondary containment; no produced water escaped the containment. A vacuum truck was dispatched to pick up any free standing liquids. There were approximately 40 bbls recovered. An Emergency Response Team arrived at the release area and began continuous abatement of the impacted area. Visibly stained soil was excavated and hauled away for disposal at a state approved facility.

Describe Area Affected and Cleanup Action Taken.* Approximately 2,300 square feet of surface area was impacted by the release. Soil samples will not be collected from release area due to finding a poly liner while removing contaminated soil. All contaminated soil has been removed and hauled for disposal and the tank battery liner has been covered with clean caliche.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins	Approved by District Supervisor: Environmental Specialist	
Title: HE Specialist	Approval Date: 7-3-14	Expiration Date: _____
E-mail Address: bradley.blevins@chevron.com	Conditions of Approval: _____	Attached <input type="checkbox"/>
Date: 5-20-14 Phone: (575) 391-1462 ext 86424		7-14-213D-70

* Attach Additional Sheets If Necessary

NT01418 82057
Ggrid 24831

JUL 10 2014