

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**  Initial Report  Final Report

Name of Company	Oxy Permian Ltd.	Contact	Chancey Summers
Address	1017 W. Stanolind Rd, Hobbs, NM 88240	Telephone No.	(575) 397-8216
Facility Name	EC Hill B Federal #20	Facility Type	Well location
Surface Owner	DK Boyd	Mineral Owner	
		API No.	30-025-33495

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	34	23S	37E	1300	South	2280	East	Lea

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**


Type of Release	Produced Water	Volume of Release	10 bbls	Volume Recovered	0 bbls
Source of Release	Polish rod liner on well head failed	Date and Hour of Occurrence	10/04/2013	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Geoffrey Leking-NMOCD; Jennifer Van Curen-BLM		
By Whom?	Chancey Summers	Date and Hour	10/07/2013 @ 10:15 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
The polish rod liner on the well head failed causing 10 bbls of produced water to leak onto the ground. No fluids were recovered and the rod liner was tightened to prevent further leaking.

Describe Area Affected and Cleanup Action Taken.\*  
The area affected was approximately 30' x 20' with all of the leak staying on location. Remediation will be conducted in accordance with a plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Chancey Summers	Approved by Environmental Specialist: 	
Title: HES Specialist	Approval Date: 8-4-14	Expiration Date: 10-7-19
E-mail Address: Chancey.Summers@oxv.com	Conditions of Approval: Site Supts require of immediate removal area as per NMOCD guides.	Attached <input type="checkbox"/> IRP-3211
Date: 10/15/13 Phone: (575) 397-8216	Submit form C-141 by 10-7-14	

\* Attach Additional Sheets If Necessary

AUG 04 2014

Original 16696  
N70142 65014  
P70142 650269