

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

~~HOBBS OCD~~

AUG 7 2014

RECEIVED

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1320 South St. Francis Dr.  
Santa Fe, NM 87505

HOBBS OCD

AUG 6 2014

RECEIVED

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

Initial Report  Final Report

Name of Company: Burgundy Oil and Gas of New Mexico	Contact: Ben Taylor
Address: 401 W Texas Suite 1003 Midland, TX 79701	Telephone No. 432-684-4033
Facility Name: Childress Road Leak	Facility Type: Gas Production

Surface Owner Federal	Mineral Owner Federal	API No. 30-025-64319 (nearest facility) <b>-04176</b>
-----------------------	-----------------------	---

#### LOCATION OF RELEASE

Unit Letter	Section 3	Township 20S	Range 36E	Feet from the	North/South Line	Feet from	East/West Line	County Lea
-------------	--------------	-----------------	--------------	---------------	------------------	-----------	----------------	---------------


Latitude: 32.60033 Longitude -103.34065

#### NATURE OF RELEASE

Type of Release: Produced water/crude	Volume of Release unknown	Volume Recovered unknown
Source of Release: Flowline	Date and Hour of Occurrence	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? DFSI Mike Burton SR Project Manager	
By Whom? Ben Taylor	Date and Hour: 07/23/14 3:29	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* NA		
Describe Cause of Problem and Remedial Action Taken.* A rupture occurred in a Flow line located off of the Childress lease road.		
Describe Area Affected and Cleanup Action Taken. This created an impact to pasture area measuring 2,657 sq. ft.. DFSI was retained to remediate the site.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

#### OIL CONSERVATION DIVISION

Signature:		
Printed Name: Ben Taylor	Approved by Environmental Specialist:	
Title: Field Foreman	Approval Date: 8-6-14	Expiration Date: 10-8-14
E-mail Address: btaylor.bogi@att.net	Conditions of Approval: SITE samples required	Attached <input type="checkbox"/>
Date: 08/05/14 Phone: 432-557-2684	IRP-3212	

\* Attach Additional Sheets If Necessary

Delimitate & remediate area as per NMOCD guides - Submit final C-141 by 10-8-14

Og rid 3044  
A701421 831023  
P701421 831134