

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OCD

Form C-141
Revised August 8, 2011
AUG 8 2014
Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	Oxy Permian Ltd.	Contact	Chancey Summers
Address	1017 W. Stanolind Rd, Hobbs, NM 88240	Telephone No.	(575) 397-8216
Facility Name	Buckeye State Com East Oil Tank	Facility Type	Gathering
Surface Owner	State	Mineral Owner	API No. 30-025-24237(nearest well)

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	20	17S	35E					Lea County, NM

Latitude: N 32.82197° Longitude: W 103.47354°

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	86 bbls	Volume Recovered	50 bbls
Source of Release	Internal corrosion caused a hole to form 6 inches from the bottom of the tank	Date and Hour of Occurrence	05/05/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Geoffrey Leking, NMOCD		
By Whom?	Kathy Purvis, BBC International	Date and Hour	05/05/2014 @ 2:35 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Internal corrosion caused a hole to form 6 inches from the bottom of the tank on the East side. This caused 86 bbls of oil to leak onto the ground. A vacuum truck recovered 50 bbls of oil and the tank was repaired.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 100' x 20' on location. Remediation will be completed in accordance with a remediation plan approved by NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name: Chancey Summers	Approved by Environmental Specialist:		
Title: HES Specialist	Approval Date: 8-8-14	Expiration Date: 10-10-14	
E-mail Address: Chancey.Summers@oxy.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 5-19-14 Phone: (575) 397-8216	Submit final C-141 by 10-10-14.		IRP-3222

* Attach Additional Sheets If Necessary

Site samples required.
Delimited remediate area 95
per NMOCD guidelines

Og 1016696
#701422 039130
#701422 039304

AUG 08 2014