

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

AUG 8 2014

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Table with 2 columns: Field Name, Value. Fields include Name of Company (EnerVest Operating LLC), Contact (Elroy Ardoin), Address (1001 Fannin Street), Telephone No. (713) 495 6534, Facility Name (Bitsy Federal #1 SWD), Facility Type (SWD).

Table with 3 columns: Surface Owner, Mineral Owner (BLM), API No. (025.33398).

LOCATION OF RELEASE

Table with 8 columns: Unit Letter, Section (7), Township (T23S), Range (R32E), Feet from the North/South Line, Feet from the East/West Line, County (Lea County).

Latitude 32.32080 Longitude 103.70727

NATURE OF RELEASE

Table with 3 columns: Description of Release, Volume of Release (50bbls), Volume Recovered (5bbls). Includes source (Nipple at wellhead), date (7/30/14), and notice details.

If a Watercourse was Impacted, Describe Fully.* N/A

Describe Cause of Problem and Remedial Action Taken.* The triplex pump used to inject produced water into the wellhead developed a plunger problem resulting in considerable vibration of the injection line. The nipple at the wellhead developed a leak resulting in the spill. The pump was turned off and the well shut in. The nipple at the wellhead was replaced and the triplex pump was repaired. The triplex pump had developed a leak as well. 5bbls of fluid was recovered inside the bermed area where the pump is located. This area has a concrete berm and bottom. All fluid was recovered in this area.

Describe Area Affected and Cleanup Action Taken.* The total affected area is approximately 10,370sq.ft. An estimated 40bbls of produced water with some oil was leaked on to the location covering an area approximately 8,750sq.ft. or an average of 70ft X 125ft. An estimated 10bbls left the location in two branches. The northeast branch covered approximately 756sq.ft or an average of 96ft X 9ft. The northwest branch covered an area approximately 756sq.ft or an average of 126ft X 6ft. A consultant has been contracted to conduct remediation operations. BLM Carlsbad office has been notified as well. The remediation plan of choice is to conduct a sampling investigation and "dig and haul" operations, with contaminated soil being delivered to Lea Land Disposal. Please see attached field evaluation report.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Andy B. Price
Printed Name: Andy Price (Registered Environmental Manager)
Title: Environmental Consultant for EnerVest Operating
E-mail Address: andyprice1@clear.net
Date: 8/8/14 Phone: (713) 495 6534 (EnerVest Op)

OIL CONSERVATION DIVISION
Approved by Environmental Specialist:
Approval Date: 8-8-14 Expiration Date: 10-10-14
Conditions of Approval: Site samples required. Delimitate & remediate area as per NM OCD guidelines. Submit final C-141 by 10-10-14
Attached
IRP-3224
Ogild 143199
A70 1422 049326
P10 1422 049501

* Attach Additional Sheets If Necessary

AUG 11 2014