

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

AUG 8 2014

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	Oxy Permian Ltd.	Contact	Chancey Summers
Address	1017 W. Stanolind Rd, Hobbs, NM 88240	Telephone No.	(575) 397-8216
Facility Name	Red Tank 34 Federal #2 CTB	Facility Type	Gathering

Surface Owner	BLM	Mineral Owner		API No.	30-025-31932
---------------	-----	---------------	--	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	34	22S	32E					Lea

Latitude N 32.34968° Longitude W 103.65624°

NATURE OF RELEASE


Type of Release	Oil	Volume of Release	30 bbls	Volume Recovered	24 bbls
Source of Release	Hammer union on 2" circulating line was replaced and was not tightened properly	Date and Hour of Occurrence	04/08/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Geoffrey Leking-NMOCD, Jennifer Van Curen-BLM		
By Whom?	Jennifer Gilkey	Date and Hour	04/09/2014 @ 5:27 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
The hammer union on a 2" circulating line was replaced but not tightened properly causing 30 bbls of oil to leak onto the ground. 24 bbls of oil were recovered via vacuum truck and the hammer union was properly tightened.

Describe Area Affected and Cleanup Action Taken.*
The affected area is approximately 9' x 25' on location and inside the berm area around the tanks. Remediation will be completed in accordance with an approved remediation plan by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Chancey Summers	Approved by Environmental Specialist: 	
Title: HES Coordinator	Approval Date: 8-11-14	Expiration Date: 10-13-14
E-mail Address: Chancey_Summers@oxy.com	Conditions of Approval: Site Supplies required	Attached <input type="checkbox"/>
Date: 4-15-14 Phone: (575) 397-8216		IRP-3225

* Attach Additional Sheets If Necessary

Belmonte Remediate area
as per NMOCD guidelines.
Submit final C-141 by
10-13-14
ogrid 16696
n7014 22 33 3460
p70 14 22 3342 25

AUG 11 2014