

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

HOBBS OCD

AUG 13 2014

RECEIVED

Form C-14  
Revised October 10, 200.

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company	COG OPERATING LLC	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	GOLDENEYE 18 FEDERAL COM #001	Facility Type	TANK BATTERY

Surface Owner	FEDERAL	Mineral Owner		Lease No. (API#)	30-025-39742
---------------	---------	---------------	--	------------------	--------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	18	24S	32E					LEA

Latitude 32 12.626      Longitude 103 43.362

**NATURE OF RELEASE**

Type of Release	Produced water	Volume of Release	100bbbls	Volume Recovered	0bbbls
Source of Release	Victaulic clamp	Date and Hour of Occurrence	06-23-2013	Date and Hour of Discovery	06-23-2013 8:45am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Geoffrey R. Leking - NMOCD		
By Whom?	Michelle Mullins	Date and Hour	06-24-2013 11:34am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The nuts and bolts on the Victaulic clamp came loose and caused the release. A new Victaulic clamp has been placed on the flowline to prevent reoccurrence.

Describe Area Affected and Cleanup Action Taken.\*

Initially 100bbbls of produced water was released due to a Victaulic clamp failure. We were unable to recover any fluid. The spill was in the adjacent pasture. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a work plan to the NMOCD/BLM for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		<b>OIL CONSERVATION DIVISION</b>	
Printed Name:	Robert Grubbs Jr.	Approved by District Supervisor:	
Title:	Senior Environmental Coordinator	Approval Date:	8-14-14
E-mail Address:	rgrubbs@concho.com	Expiration Date:	10-16-14
Date:	07-03-2013	Phone:	432-661-6601
		Conditions of Approval:	Attached <input type="checkbox"/>
		Site Specific Report Debate & resolve in per NMOCD guidance submit final C-141 by 10-16-14	1 RP-3289 og:nd 21 8755 nto 1422 631220 p 701422 631392

\* Attach Additional Sheets If Necessary

AUG 14 2014