

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

*NA 1423031875* OPERATOR  Initial Report  Final Report

Name of Company	COG OPERATING LLC <i>229137</i>	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name:	Kudu Fee #1H	Facility Type:	Battery
Surface Owner: Fee	Mineral Owner: Fee	Lease No. (API#) 30-015-42029	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	13	24S	27E	200	South	2350	East	Eddy

Latitude N32' 12.600' Longitude W104' 08.571

**NATURE OF RELEASE**

Type of Release Oil and Produced Water	Volume of Release Oil: 25 bbls ; PW: 150 bbls	Volume Recovered Oil: 24 bbls ; PW: 150 bbls
Source of Release Gasket failure on water knock out	Date and Hour of Occurrence 8-12-2014 6:00 am	Date and Hour of Discovery 8-12-2014 8:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - OCD	
By Whom? Amanda Trujillo	Date and Hour 8-15-2014 5:00 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* A gasket on the water knockout failed causing the release of fluid. The gasket was replaced.		
Describe Area Affected and Cleanup Action Taken.* This release occurred within a lined containment. Vacuum trucks were dispatched and recovered all standing fluid. This location has been returned to its prior condition.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <i>A Trujillo</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amanda Trujillo	Approved by District Supervisor: <i>[Signature]</i>	
Title: Senior Environmental Coordinator	Approval Date: <i>8/18/14</i>	Expiration Date: <i>NA</i>
E-mail Address: atrujillo@concho.com	Conditions of Approval: <i>Final</i>	Attached <input type="checkbox"/>
Date August 15, 2014 Phone: 575-748-6940		

\* Attach Additional Sheets If Necessary

*2RP-2445*

**NM OIL CONSERVATION**

ARTESIA DISTRICT

AUG 15 2014

RECEIVED

## **Patterson, Heather, EMNRD**

---

**From:** Amanda Trujillo <ATrujillo@concho.com>  
**Sent:** Friday, August 15, 2014 3:54 PM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD  
**Cc:** HSE-Environmental; Production Mail  
**Subject:** (Notification/C-141 Initial Final) Kudu Fee #1H (30-015-42029)  
**Attachments:** 8-12-2014 Kudu Fee #1H (TB) Inital - Final.pdf

Mr. Bratcher,

COG Operating LLC is reporting a release at the **Kudu Fee #1H (30-015-42029)**.

The release occurred at 6:00 am on 08/12/2014.

**Released:** 25 bbls Oil ; 150 bbls PW

**Recovered:** 24 bbls Oil ; 150 bbls PW

This release was caused by a gasket failure on the water knockout. Attached is a C-141 Initial/Final for your consideration. If you have any additional questions please feel free to contact me.

Thank you,

### **Amanda Trujillo**

Senior Environmental Coordinator

COG Operating LLC

Cell: 505.350.1336

Office: 575.748.6930

[atrujillo@concho.com](mailto:atrujillo@concho.com)

2208 W. Main St.

Artesia , NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.