

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

*NAB1424538884* OPERATOR  Initial Report  Final Report

Name of Company: BOPCO, L.P. <i>2100737</i>	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: JRU-62 The flow line spill is 1600 ft. north of the well pad.	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-35340	

**LOCATION OF RELEASE**

Unit Letter J	Section 1	Township 23S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude N 32.334352 Longitude W 103.832156

**NATURE OF RELEASE**

Type of Release: Crude oil and produced water	Volume of Release: 2 bbls crude oil and 8 bbls water	Volume Recovered: None
Source of Release: 2 7/8" flow line	Date and Hour of Occurrence: 8/31/14 time unknown	Date and Hour of Discovery: 8/31/14 at 11:44 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

**NM OIL CONSERVATION**  
ARTESIA DISTRICT  
SEP 02 2014

**RECEIVED**

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
The flow line leaked due to external corrosion. The well was shut in and a temporary repair clamp was installed on the affected pipe.

Describe Area Affected and Cleanup Action Taken.\*  
The spill impacted approximately 720 sq. ft. of caliche road. All of the fluid soaked into the roadway. The impacted soil will be excavated and hauled to Lea Lands. The final remediation will be in accordance to the NMOCD and BLM guidelines for spill remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Tony Savoie	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Waste Management and Remediation Specialist	Approval Date: <i>9/2/14</i>	Expiration Date: <i>N/A</i>
E-mail Address: <a href="mailto:tasavoie@basspet.com">tasavoie@basspet.com</a>	Conditions of Approval: Remediation per OCD Rule & Guidelines. <b>SUBMIT REMEDIATION</b>	Attached <input type="checkbox"/>
Date: 9/2/14 Phone: 432-556-8730	PROPOSAL NO LATER THAN: <i>10/2/14</i>	

*2RP-2465*

\* Attach Additional Sheets If Necessary

Hudson 1-Fed SWD

JRU-36

JRU-10

Spill 8-31-14

JRU

JRU-62

Google