

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

*AB1425828L01L0* OPERATOR  Initial Report  Final Report

Name of Company: COG Operating LLC <i>217955</i>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Perkins SWD #1	Facility Type: Battery

Surface Owner: Fee	Mineral Owner: Fee	API No. 30-015-23849
--------------------	--------------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	30	26S	29E	1980	North	1980	East	Eddy

Latitude 32.0154573312528 Longitude -104.021637216979

**NATURE OF RELEASE**

Type of Release: Produced Water	Volume of Release: 15 bbls	Volume Recovered: 15 bbls
Source of Release: Corroded victrollic clamp	Date and Hour of Occurrence: 8-28-2014 8:30 am	Date and Hour of Discovery: 8-28-2014 8:30 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Victrollic clamp eroded on valve connection on the header inside a lined containment. Repairs were made to the header and the clamp was replaced. A vacuum truck was dispatched to recover any standing fluid.

Describe Area Affected and Cleanup Action Taken.\*

The release occurred with a lined containment. Any recovered fluid or impacted material was disposed of at an NMOCD approved facility.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>A. Trujillo</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Senior Environmental Coordinator	Approval Date: <i>9/12/14</i>	Expiration Date: <i>NA</i>
E-mail Address: <a href="mailto:atrujillo@concho.com">atrujillo@concho.com</a>	Conditions of Approval: <i>Final</i>	Attached <input type="checkbox"/>
Date: September 11, 2014 Phone: 575-748-6940		

\* Attach Additional Sheets If Necessary

*2RP-2484*

## **Patterson, Heather, EMNRD**

---

**From:** Amanda Trujillo <ATrujillo@concho.com>  
**Sent:** Thursday, September 11, 2014 4:37 PM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD  
**Subject:** (Notification/Initial-Final C-141) Perkins SWD #1 (30-015-23849)  
**Attachments:** 08-28-2014 Perkins SWD #1 (TB) Inital-Final.pdf

Mr. Bratcher,

COG Operating LLC is reporting a release at the **Perkins SWD #1 (30-015-23849)**.

Unit U Section 30 Township 26S Range 29E

The release occurred at 8:30 am on 08/28/2014.

**Released:** 15 bbls PW

**Recovered:** 13 bbls PW

This release was caused by a corroded vitriolic clamp on a valve connection. The release occurred in a lined facility. Attached is a C-141 Initial/Final for your consideration. If you have any additional questions please feel free to contact me.

Thank you,

### **Amanda Trujillo**

Senior Environmental Coordinator

COG Operating LLC

Cell: 505.350.1336

Office: 575.748.6930

[atrujillo@concho.com](mailto:atrujillo@concho.com)

2208 W. Main St.

Artesia , NM 88210



**CONFIDENTIALITY NOTICE:** The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

**CONFIDENTIALITY NOTICE:** The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.