

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**  Initial Report  Final Report

Name of Company	Oxy Permian Ltd.	Contact	Chancey Summers
Address	1017 W. Stanolind Rd, Hobbs, NM 88240	Telephone No.	(575) 397-8216
Facility Name	Federal 12 #1 South CTB	Facility Type	Gathering
Surface Owner	BLM	Mineral Owner	API No.30-015-26742(nearest well)

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	12	22S	31E					Eddy County, NM

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release	Produced Water	Volume of Release	45 bbls	Volume Recovered	40 bbls
Source of Release	Pump failure caused tank overflow	Date and Hour of Occurrence	11/17/2013	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-NMOCD; James Amos- BLM		
By Whom?	Chancey Summers	Date and Hour	11/19/13 @ 9:04am and 11/18/13 @ 2:07pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

A bearing on the water transfer pump went out causing the pump to fail and the water production tank to overflow. The overflow caused 45 bbls of produced water to leak onto the ground. A vacuum truck recovered 40 bbls of the leaked fluids and the pump was replaced.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 30' x 30' on location. Remediation was completed in accordance with the remediation plan approved Mike Bratcher of NMOCD in a meeting on 02/19/2014 and approved by Jennifer Van Curen of the BLM via email on 02/24/2014.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		<b>OIL CONSERVATION DIVISION</b>	
Printed Name:	Chancey Summers	Approved by Environmental Specialist:	
Title:	HES Specialist	Approval Date:	8/22/14
E-mail Address:	Chancey.Summers@oxy.com	Expiration Date:	NA
Date:	4-29-14	Conditions of Approval:	Final
Phone:	(575) 397-8216	Attached	<input type="checkbox"/>

\* Attach Additional Sheets If Necessary

2RP-2097