

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1435037409 OPERATOR Initial Report Final Report

Name of Company: BOPCO, L.P. 8100737	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: ND 19 Federal SWD No.001	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-39713	

LOCATION OF RELEASE

Unit Letter A	Section 19	Township 24S	Range 30E	Feet from the 516	North/South Line North	Feet from the 705	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude N 32.208897 Longitude W 103.914495

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 226 bbls.	Volume Recovered: 85 bbls.
Source of Release: Flex gasket on wellhead	Date and Hour of Occurrence: 12/3/14 at approximately 7:30 am	Date and Hour of Discovery: 12/3/14 at approximately 7:30 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher NMOCD	
By Whom? Bradley Blevins	Date and Hour: 12/13/14 at approximately 4:00 p.m. 3:25 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse NM OIL CONSERVATION ARTESIA DISTRICT	

If a Watercourse was Impacted, Describe Fully.*
DEC 15 2014
RECEIVED

Describe Cause of Problem and Remedial Action Taken.*
A flex gasket on the wellhead failed releasing produced water on the well pad. All of the free standing fluid was recovered and the gasket was replaced.

Describe Area Affected and Cleanup Action Taken.*
The spill impacted approximately 15,300 sq.ft. of caliche well pad and approximately 4,000 sq.ft. pasture area. The impacted area was left as is pending final remediation. There was a significant area of produced water impact on the well pad prior to the release that was scheduled to be cleaned up due to the possible construction of a SWD facility on the well pad.
The spill area will be cleaned up in accordance to the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by Environmental Specialist <i>Mike Bratcher</i>	
Title: Waste Management and Remediation Specialist	Approval Date: 12/16/14	Expiration Date: N/A
E-mail Address: tasavoie@basspet.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines	
Date: 12/15/14 Phone: 432-556-8730	Attached <input type="checkbox"/> SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: 1/16/15 **2RP-2463**

FIELD SPILL REPORT

Distribution List: CJ Barry, TA Savoie, RL Gawlik, B. Biehl, JR Smitherman, SF Johnson, FD Schoch, G Fletcher, J Fuqua, A Ruth, A Thompson, S Walters, B Blevins, G Goodgame

DATE: December 3, 2014

LOCATION OF SPILL SITE: ND 19 Federal SWD No. 001 (API-30-015-39713)

GPS COORDINATES (Lat & Long): 32.208897 -103.914495 (UL-A-19-24S-30E) 516 FNL & 705 FEL

ESTIMATED VOLUMES (Oil & Water Separately):

*If BBLs Recovered are not available at time of Initial Report: Send in Followup report when numbers are known

Volume spilled:		BBls Spilled	*BBls Recovered	Net Spilled		BBls Spilled	*BBls Recovered	Net Spilled
On ground /or earth berm -	Oil:			0	Water:	226	85	141
Contained in impervious liner -	Oil:			0	Water:			0
	Total:	0	0	0	Water:	226	85	141


DESCRIPTION (What happened?):

Bottom of flex gasket failed on the wellhead, Releasing PW to the ground surface and off wellpad

SPILL RESPONSE (How was the spill cleaned up?):

Vacuum trucks recovered 85 bbls. NMOCD was notified

PICTURE ATTACHMENT:



2/2/2014 2:11pm

ND 19 SWD

ND 19 FED SWD 01PM

© 2014 Google

Google

1396

Imagery Date: 2/13/2014 32°12'31.00" N 103°54'52.69" W elev. 3190 ft

Savoie, Tony A.

From: Blevins, Bradley
Sent: Thursday, December 04, 2014 9:56 AM
To: mike.bratcher@state.nm.us; Amos, James
Cc: Blevins, Bradley; Savoie, Tony A.
Subject: ND Federal SWD 1- Release
Attachments: photo 1.JPG; photo 1.jpg; photo 1.jpg; photo 2.jpg; photo 3.jpg

Mike,

Per our conversation yesterday afternoon here is a follow up on the Release at the ND Federal SWD 1. Most of the fluid remained on the well pad, although some did escape on the SW corner of the well pad and ran back to the west. Attached are a few photos. If you have any questions or concerns please let me know. I will follow up with an initial C-141.

PW released- 226
PW recovered- 85

Brad Blevins
Assistant Remediation Foreman
BOPCO, LP
522 W. Mermod, Suite 704
Carlsbad, NM 88220
Office-575-887-7329
Cell-1-432-214-3704
bblevins@basspet.com

ENVIRONMENTAL RELEASE NOTIFICATION

Call-In Sheet

Date: 12/3/14

Notice received by: NB

BDACO
Name of Company/Phone #

ND 19 Fed 1 SWD
Facility Name

015-39713
API #

19 24s-306.
Sec. Township Range

12/3/14
Date of Occurrence

8 AM
Date/Hour of Discovery

PW
Type of Release

> 25 bbls
Volume of Release

unk @ this time
Volume Recovered

Briefly Describe Cause of Problem and action taken: Flange Fracture @ Headline

Bradley Blewins 432-214-3704
Notice given by: Name/ Company

3:25 PM 12/3/14
Date/Hour Immediate Notice given

Date C-141 received: 12/15/14

2RP- 26603

FLARE NOTIFICATION

Call-In Sheet

Date:

Notice received by:

Name of Company/Phone #

Facility Name

Date of Occurrence

Date/Hour of Flare

Type of Release

Flared MCF Volume

Volume Recovered

Briefly Describe Cause of Problem and action taken:

Notice given by: Name/ Company

Date/Hour Immediate Notice given

Date C-141 received:

2RP-