

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**0AB1435729198**      **OPERATOR**       Initial Report       Final Report

Name of Company: COG Operating LLC <b>229137</b>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Barn Owl Federal #3H	Facility Type: Battery
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-41283	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	18	26S	27E	380	South	1890	West	Eddy

Latitude 32.036193428063 Longitude -104.231672940042

**NATURE OF RELEASE**

Type of Release: Oil	Volume of Release: 15 bbls Oil	Volume Recovered: 14 bbls Oil
Source of Release: Over run tanks	Date and Hour of Occurrence: 12/10/2014 11:30 am	Date and Hour of Discovery: 12/10/2014 11:30 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* The release was caused an alarm malfunction on the high oil alarm. Vacuum trucks were dispatched to recover the standing fluid.		
Describe Area Affected and Cleanup Action Taken.* This release occurred within a lined facility and all fluids were able to be recovered and the facility put back into operation.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <i>A Trujillo</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Senior Environmental Coordinator	Approval Date: <i>12/23/14</i>	Expiration Date: <i>NA</i>
E-mail Address: atrujillo@concho.com	Conditions of Approval: <i>Final</i>	Attached <input type="checkbox"/>
Date: December 22, 2014      Phone: 575-748-6940		

**RECEIVED**  
 DEC 22 2014  
 NMOCD ARTESIA

\* Attach Additional Sheets If Necessary

*229-2084*

## **Patterson, Heather, EMNRD**

---

**From:** Amanda Trujillo <ATrujillo@concho.com>  
**Sent:** Monday, December 22, 2014 5:16 PM  
**To:** Bratcher, Mike, EMNRD; jlrobertson@blm.gov; james\_amos@blm.gov; Hughes, Solomon; Patterson, Heather, EMNRD  
**Subject:** (Notification-C-141 Initial Final) Barn Owl Federal #3H (30-015-41283)  
**Attachments:** 12-10-2014 Barn Owl Federal #3H (TB) Initial-Final.pdf

Mr. Bratcher/Mr. Amos,

COG Operating LLC is reporting a release on the Barn Owl Federal #3H (30-015-41283).  
Unit N, Section 18 Township 26S Range 27E  
The release occurred at 11:30 pm on 12/10/2014.  
Released: 15 bbls Oil  
Recovered: 14 bbls Oil

This release was caused by an alarm malfunctioning that caused an inlet valve to fail and over run tanks, all fluid contained within the lined facility. Attached is a C-141 for your consideration. If you have any additional questions please feel free to contact me.

Thank you,

### **Amanda Trujillo**

Senior Environmental Coordinator  
COG Operating LLC  
Cell: 505.350.1336  
Office: 575.748.6930  
[atrujillo@concho.com](mailto:atrujillo@concho.com)

2407 Pecos Ave.  
Artesia , NM 88210



**CONFIDENTIALITY NOTICE:** The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

**CONFIDENTIALITY NOTICE:** The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review,

dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

**CONFIDENTIALITY NOTICE:** The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.