

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT Form C-141
Revised August 8, 2011
JAN 26 2015
Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.
RECEIVED

Release Notification and Corrective Action

NAB1502727312 **OPERATOR** Initial Report Final Report

Name of Company: BOPCO, L.P. 210731	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU-158 Tank Battery	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-31690	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	7	24S	30E	660	North	660	East	Eddy

Latitude N 32.237661 Longitude W 103.913889

NATURE OF RELEASE

Type of Release: Crude oil and produced water	Volume of Release: 27 bbls crude oil and 8 bbls produced water	Volume Recovered: 20 bbls crude oil and 4 bbls produced water
Source of Release: Heater-treater	Date and Hour of Occurrence: 1/23/15 time unknown	Date and Hour of Discovery: 1/23/15 approx. 10:35 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher, H. Patterson, and Jim Amos	
By Whom? Tony Savoie	Date and Hour: 1/23/15 at 12:52 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* A gasket failed on the heater-treater fire tube. The heater was by-passed and the gasket was replaced.		
Describe Area Affected and Cleanup Action Taken.* The spill impacted approximately 2100 sq. ft. of tank battery caliche containment area and approximately 250 sq. ft. of pasture was misted with crude oil. There was no vegetation in the pasture area impacted. A vacuum truck recovered the free standing fluids. The stained area was left as is pending the final remediation. The area will be cleaned up in accordance with the NMOCD and BLM remediation guidelines.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <i>Tony Savoie</i>	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Signed By: <i>Mike Barron</i> Approved by Environmental Specialist:	
Title: Waste Management and Remediation Specialist	Approval Date: <i>1/27/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: tasavoie@basspet.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> Attached <input type="checkbox"/>	
Date: <i>1/26/15</i> Phone: 432-556-8730	SUBMIT REMEDIATION PROPOSAL NO LATER THAN: <i>2/27/15</i>	

* Attach Additional Sheets If Necessary

2RP-2762

57:45 pm

3:00 pm

PLU-158

Spill area

Bermed area

© 2015 Google

Goog

1996

Imagery Date: 2/13/2014 lat 32.237541° lon -108.914195° elev 3251 ft