

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

FEB 4 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1505853407

OPERATOR

Initial Report Final Report

Name of Company Linn Operating Inc. <i>2109324</i>	Contact E.L. Gonzales
Address 2130 W Bender Blvd Hobbs, NM 88240	Telephone No. 575-738-1739
Facility Name JL Keel A #12	Facility Type Injection

Surface Owner Federal	Mineral Owner	API No. 30-015-05100
-----------------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter A	Section 07	Township 17S	Range 31E	Feet from the 660	North/South Line North	Feet from the 660	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.85442 Longitude -103.90174

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 4 bbls	Volume Recovered 3 bbls
Source of Release Pipeline-FG	Date and Hour of Occurrence 02/03/2015	Date and Hour of Discovery 02/03/2015 11:00am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* I was notified by the injection plant operator that the pressure was low on the header injection line #3. As I drove out the line I found the leak by the between the tinorns containing the block valves. Driving directions to site: from CR221 & US 82 go N on 221 1.4 miles, go R/NE .5m, E .4m, N.5m to Keel A #12

Describe Area Affected and Cleanup Action Taken.* Leak is approx. 50yds N in pasture. Affected area roughly 8'widex25' long

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: E.L. Gonzales	Approved by Environmental Specialist:	
Title: Production Supervisor	Approval Date: <i>2/27/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: elgonzales@linenergy.com	Conditions of Approval:	
Date: 02/04/2015 Phone: 505-504-8002	Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

LATER THAN: 3/27/15

2RP-2843