

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210.
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESTA DISTRICT

Form C-141
Revised August 8, 2011

MAR 05 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1506538521

OPERATOR

Initial Report Final Report

Name of Company: COG Operating LLC <i>229137</i>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Loco Hills SWD #1	Facility Type: SWD

Surface Owner: State	Mineral Owner:	API No. 30-015-31635
----------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter P	Section 36	Township 17S	Range 30E	Feet from the 660'	North/South Line South	Feet from the 860'	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.7856127233776 Longitude -103.919670657623

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 130 bbls	Volume Recovered: 130 bbls
Source of Release: Flowline within battery	Date and Hour of Occurrence: 3/3/2015 10:00 am	Date and Hour of Discovery: 3/3/2015 10:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD	
By Whom? Amanda Trujillo	Date and Hour: 3/5/2015 6:30 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
A flowline off the H-pump became plugged and caused the release. Vacuum trucks were dispatched to recover all standing fluid.

Describe Area Affected and Cleanup Action Taken.*
This release occurred within a falcon lined facility. All fluid was able to be recovered.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>A Trujillo</i>	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Senior Environmental Coordinator	Approval Date: <i>3/6/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: atrujillo@concho.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: March 5, 2015	Phone: 575-748-6940	

* Attach Additional Sheets If Necessary

ZRP-2862

Patterson, Heather, EMNRD

From: Amanda Trujillo <ATrujillo@concho.com>
Sent: Thursday, March 05, 2015 6:25 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Subject: (Notification/C-141 Initial-Final) Loco Hills SWD #1 (30-015-31635)
Attachments: 3-3-2015 Loco Hills SWD #1 (TB) Initial-Final.pdf

Mr. Bratcher,

COG Operating LLC is reporting a release on the Loco Hills SWD #1 (30-015-31635)
Unit P Section 36, Township 17S Range 30E
The release occurred at 10:00 am on 3/3/2015
Released: 130 bbls PW
Recovered: 130 bbls PW

A flowline off the H-pump became plugged and caused the release. Vacuum trucks were dispatched to recover all standing fluid. This release occurred within a falcon lined facility. All fluid was able to be recovered. Attached is a C-141 Initial-Final for your consideration. If you have any additional questions please feel free to contact me.

Thank you,

Amanda Trujillo

Senior Environmental Coordinator
COG Operating LLC
Cell: 505.350.1336
Office: 575.748.6930
atrujillo@concho.com

2208 W. Main St.
Artesia , NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.