


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

PAB1435830421 Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company **OXY USA WTP LP** *192463* Contact **CAMPBELL, RODNEY**
 Address **329 Marathon Rd, Lakewood** Telephone No. **(575) 628-4167**
 Facility Name **INDIAN BASIN GAS PLANT** Facility Type **GAS PROCESSING FACILITY**

Surface Owner _____ Mineral Owner **INDIAN BASIN** Lease No. _____

LOCATION OF RELEASE

| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
|-------------|---------|----------|-------|---|------------------|-------------------|----------------|--------|
| G | 23 | 21-S | 23-E | | | | | Eddy |
| | | | | <i>32.464584</i> | | <i>104.574456</i> | | |
| | | | | Latitude 32°27'52.502" Longitude 104°34'28.004" | | | | |

NATURE OF RELEASE

| | | |
|--|--|---|
| Type of Release Gas | Volume of Release 678.9 MCF | Volume Recovered 0 |
| Source of Release Residue Flare | Date and Hour of Occurrence 1/15/2014 11:07:00 AM | Date and Hour of Discovery 1/15/2014 11:07:00 AM |
| Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? MIKE BRATCHER | |
| By Whom? RODNEY CAMPBELL | Date and Hour 01/16/2014 12:55PM VOICE-MAIL | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. N/A | |
| If a Watercourse was Impacted, Describe Fully.* N/A | | |
| Describe Cause of Problem and Remedial Action Taken.* Cause: OXY INDIAN BASIN GAS PLANT FLARED RESIDUE SALES GAS FOR 12 MINUTES DUE TO HIGH OXYGEN CONTENT. Remedial Action Taken: OPERATIONS ATTEMPTED TO CHECK STABILIZER DISCHARGE METER AND INLET METER BUT DUE TO SHORT DURATION OF EVENT, SOURCE OF OXYGEN COULDN'T BE DETERMINED. | | |
| Describe Area Affected and Cleanup Action Taken.* N/A | | |

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | |
|---|--------------------------------------|-----------------------------------|
| Signature: <i>R. Campbell</i> | OIL CONSERVATION DIVISION | |
| Printed Name: RODNEY CAMPBELL | Approved by District Supervisor | Signed By <i>Mike Bratcher</i> |
| Title: <i>HES Specialist</i> | Approval Date: 3/11/15 | Expiration Date: N/A |
| E-mail Address: RODNEY_CAMPBELL@OXY.COM | Conditions of Approval: FINAL | Attached <input type="checkbox"/> |
| Date: 1-16-14 Phone: (575) 628-4167 | | |

* Attach Additional Sheets If Necessary

2RP-2878