

Bratcher, Mike, EMNRD

From: Tavarez, Ike [Ike.Tavarez@tetrattech.com]
Sent: Monday, September 13, 2010 2:46 PM
To: Bratcher, Mike, EMNRD; Terry Gregston (terry_gregston@nm.blm.gov)
Cc: Pat Ellis; Joshua Russo
Subject: COG - Sampling Notifications - Schley Federal #11 TB and Electra North TB

COG Operating LLC

Schley Federal #11 (flowline)
Section 23, T17S, R29E
Eddy County, New Mexico

30-015-32134 2RP. 431

Electra North Federal Tank Battery
Section 10, T17S, R30E
Eddy County, NM

Terry and Mike,

Tetra Tech will be onsite at the Schley Federal #11 flow line leak to collect soil samples (hand auger) to assess the spill area on Tuesday September 14, 2010 and the Electra Federal North Tank Battery on Wednesday September 15, 2010. Please call me if you have any questions. Thanks

Ike Tavarez, PG | Senior Project Manager

Main: 432.682.4569 | Fax: 432.682.3946 | Cell: 432.425.3878

Ike.Tavarez@tetrattech.com

Tetra Tech | Complex World, Clear Solutions™

1910 North Big Spring | Midland, TX 79705 | www.tetrattech.com

PLEASE NOTE: This message, including any attachments, may include privileged, confidential and/or inside information. Any distribution or use of this communication by anyone other than the intended recipient is strictly prohibited and may be unlawful. If you are not the intended recipient, please notify the sender by replying to this message and then delete it from your system.

Bratcher, Mike, EMNRD

From: Terry_Gregston@blm.gov
Sent: Thursday, September 16, 2010 4:52 PM
To: Joshua Russo
Cc: Tavarez, Ike; james_amos@nm.blm.gov; Bratcher, Mike, EMNRD; Pat Ellis
Subject: Re: C-141 - Schley Federal #11 Flowline
Attachments: Schley Federal 11 flowline spill map-082810.jpg

Joshua and Pat,

I inspected the Schley Federal 11 flowline spill yesterday and mapped the visible salts from the spill point downslope. The spill is larger than indicated on your spill report. Fluids ran down the road to the Empire Abo Unit 50, then followed drainage off the western edge of that pad to the south, then southeast. I tracked the spill/salts down to an older spill in the flowline corridor about 200 feet northwest of the Green A Federal 10 SWD unit. At this point, it appeared that your spill overran and/or comingled with an older spill. I do not know whose flowline the older spill belongs to.

I am attaching a spill map of the spill as I GPS'd it yesterday.

All of the spill path area is covered by pre-existing archeological surveys, so it is okay to proceed with cleanup. However, the older spill complicates things somewhat.

Terry Gregston
Environmental Protection Specialist
Bureau of Land Management
620 E. Greene St.
Carlsbad, NM 88220
Office (575) 234-5958
Fax (575) 234-5927

Spill-Saltwater 0.3992

EMPIRE ABO UNIT #050

EMPIRE ABO UNIT #050

SCHLEY FEDERAL #003

029

GREEN A FEDERAL #010

