

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NAB1508252431

OPERATOR

Initial Report Final Report

Name of Company	Oxy Permian Ltd. <i>10696</i>	Contact	Christopher Jones
Address	1502 W. Commerce Dr., Carlsbad, NM	Telephone No.	(575) 628-4121
Facility Name	Sterling Silver 3 Federal #6 CTB	Facility Type	Battery

Surface Owner	BLM	Mineral Owner		API No.	30-01527638
---------------	-----	---------------	--	---------	-------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	3	24S	31E					Eddy

Latitude N 32.24813° Longitude W 103.76643°

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	30 bbls oil, 170 bbls produced water	Volume Recovered	20 bbls oil
Source of Release	Water transfer pump malfunction caused tank spill	Date and Hour of Occurrence	03/04/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Heather Patterson- NMOCD; Sol Hughes-BLM		
By Whom?	Kathy Purvis, BBC International	Date and Hour	03/05/2015		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Malfunction of a water transfer pump caused a tank to spill 30 bbls of oil and 170 bbls of produced water onto the ground. A vacuum truck recovered 20 bbls of oil and the pump was repaired/reset.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 50' x 50' on location within the containment area. Remediation will be completed in accordance with a remediation plan approved by both NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Chris Jones <small>Digitally signed by Chris Jones DN: cn=Chris Jones, o, ou, email=ckjones888@yahoo.com, c=US Date: 2015.03.23 10:36:53 -05'00'</small>	OIL CONSERVATION DIVISION	
Printed Name: Christopher Jones	Approved by District Supervisor: <i>[Signature]</i>	
Title: HES Specialist	Approval Date: 3/23/15	Expiration Date: N/A
E-mail Address: Christopher_jones@oxy.com	Conditions of Approval:	
Date: 3/23/15	Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO LATER THAN: <u>4/23/15</u>	

* Attach Additional Sheets If Necessary

Attached

2RP-2908

Bratcher, Mike, EMNRD

From: Kathy Purvis <kathy@bbcinternational.com>
Sent: Monday, March 23, 2015 9:55 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: christopher_jones@oxy.com; Tiffney; sara_martinez@oxy.com;
cbrunson@bbcinternational.com; kswinney@bbcinternational.com;
jgilkey@bbcinternational.com
Subject: Initial C-141, Sterling Silver 3 Federal #6 CTB
Attachments: Initial C-141, Sterling Silver 3 Federal #6 CTB.pdf

Attached is the initial C-141 for a leak that occurred at the Sterling Silver 3 Federal #6 CTB on 03/04/2015 in Eddy County, NM. Receipt notification via email is greatly appreciated.

Kathy Purvis

BBC International, Inc.
1324 W. Marland
Hobbs, NM 88240
Phone: (575) 397-6388
Fax: (575) 397-0397
Email: kathy@bbcinternational.com

Well Selection Criteria Quick Print

tbiWellMaster.api_wellno Like '30015276380000'

API Well #	Well Name and No.	Operator Name	Typ	Stat	County	Surf	UL	Sec	Twp	Rng	Ft N/S	Ft E/W	UICPrmt	Lst Insp Dt
30-015-27638-00-00	STERLING SILVER 3 FEDERAL 006	OXY USA INC	O	A	Eddy	F	F	3	24 S	31 E	1980 N	2310 W		3/23/2015