

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

APR 07 2015

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
Submitted to appropriate District Office in
accordance with 19.15.29 NMAC.

FAB1508435844
OAB1509851503

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Enterprise Field Services LLC	Contact Dina Babinski
Address PO Box 4324, Houston TX 77210	Telephone No. 210-528-3824
Facility Name Pipeline ROW, 1009 Gathering Lateral	Facility Type Gas Gathering Pipeline
Surface Owner Department of Interior/Bureau of Land Management/Department of Energy	Mineral Owner NA - Pipeline
API No. NA	

LOCATION OF RELEASE

Unit Letter M	Section 23	Township 22S	Range 30E	Feet from the 105	North/South Line South	Feet from the 381	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude N 32.37066 Longitude W -103.85719

NATURE OF RELEASE

Type of Release Natural Gas, Pipeline Liquids	Volume of Release 1147 MCF, 2 bbl pipeline liquids	Volume Recovered NA
Source of Release Pipeline Leak	Date and Hour of Occurrence 3/29/2015 14:30 MDT	Date and Hour of Discovery 3/29/2015 @ 14:30 MDT
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD District 2 Reporting Hotline	
By Whom? Osman De Leon	Date and Hour 3/29/2015 14:44 MDT	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A pipeline leak was detected by pumper passing by. Operations personnel isolated leaking portion of pipeline and proceeded with pipeline repairs following standard One-Call.

Describe Area Affected and Cleanup Action Taken.*

Approximately 2 bbl pipeline liquids spilled to the ground within pipeline right-of-way. Contaminated soil will be excavated and disposed at an approved landfill. Soil sampling will be performed to demonstrate compliance with NMOCD remediation standards.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jon Fields</i>	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Jon Fields	Approved by	Signed By <i>Mike Brannan</i>
Title: Director, Field Environmental	Approval Date: 4/8/15	Expiration Date: N/A
E-mail Address: snolan@eprod.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3-7-2015 Phone: 713-381-6595	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 5/8/15

2RP. 2937

Bratcher, Mike, EMNRD

From: Nolan, Shiver <SNolan@eprod.com>
Sent: Tuesday, April 07, 2015 9:40 AM
To: rpair@blm.gov; Bratcher, Mike, EMNRD
Cc: Babinski, Dina
Subject: Pipeline ROW 1009 Gathering Lateral
Attachments: C-141 Eddy County 1009 Gathering Line - Initial Report April 2015.pdf

Attached for your handling is the initial C-141 for the 1009 Gathering Lateral. Should you have questions or need additional information, please contact Dina Babinski at 210-528-3824.

Shiver J. Nolan
Sr. Compliance Administrator
Enterprise Products Operating LLC

This message (including any attachments) is confidential and intended for a specific individual and purpose. If you are not the intended recipient, please notify the sender immediately and delete this message.