

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources **APR 29 2015**
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.
RECEIVED

Release Notification and Corrective Action

NAB 1512157315

OPERATOR Initial Report Final Report

Name of Company: BOPCO, L.P. 260737	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: Poker Lake Unit 274 Tank Battery	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-35138	

LOCATION OF RELEASE

Unit Letter O	Section 12	Township 24S	Range 29E	Feet from the 360	North/South Line South	Feet from the 2310	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude: N 32.225443° Longitude: W 103.936917°

NATURE OF RELEASE

Type of Release: crude oil and produced water	Volume of Release: 13 bbls oil and 9 bbls water	Volume Recovered: 3 bbls oil and 2 bbls water
Source of Release: water leg connection on the heater treater failed	Date and Hour of Occurrence: 4/20/15 @ 12:24 pm	Date and Hour of Discovery: 4/20/15 @ 12:24 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD, BLM via email	
By Whom? Bradley Blevins	Date and Hour: 4/21/15 @ 10:07 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	
If a Watercourse was impacted, Describe Fully.* Not Applicable		
Describe Cause of Problem and Remedial Action Taken.* A connection on the water leg of the heater treater failed. The connection was repaired.		
Describe Area Affected and Cleanup Action Taken.* The release impacted approximately 3,700 sq. ft. of tank battery and well pad area including an area misted on the south side of the tank battery location. Vacuum truck recovered 5 bbls of fluid. The area will be remediated in accordance with the NMOCD and BLM remediation guidelines.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

OIL CONSERVATION DIVISION

Signature: <i>Bradley Blevins</i>	Approved by Environmental Specialist: <i>[Signature]</i>	
Printed Name: Bradley Blevins	Approval Date: 5/1/15	Expiration Date:
Title: Assistant Remediation Foreman	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
E-mail Address: bblevins@basspet.com	Date: 4-24-15 Phone: 432-214-3704	

REMIT REMEDIATION PROPOSAL NO
ATER THAN: 4/11/15

* Attach Additional Sheets If Necessary

ARP-2978

Patterson, Heather, EMNRD

From: Blevins, Bradley <BBlevins@BassPet.Com>
Sent: Wednesday, April 29, 2015 11:55 AM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD; Amos, James
Cc: Savoie, Tony A.; Blevins, Bradley
Subject: PLU 274 Initial C-141
Attachments: doc04264220150427080956.pdf

All,

Please find the initial C-141 for the release that occurred at the PLU 274 Battery. If you have any questions please let me know.

Thanks,

Brad Blevins
Assistant Remediation Foreman
BOPCO, LP
522 W. Mermod, Suite 704
Carlsbad, NM 88220
Office-575-887-7329
Cell-1-432-214-3704
bblevins@basspet.com

Patterson, Heather, EMNRD

From: Blevins, Bradley <BBlevins@BassPet.Com>
Sent: Tuesday, April 21, 2015 10:07 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Amos, James
Cc: Blevins, Bradley; Savoie, Tony A.
Subject: PLU 274 Release
Attachments: photo.jpg

All,

BOPCO EHS was notified of a release at the PLU 274 Battery. A connection on the water leg of the heater treater failed releasing fluid to the ground surface. All of the free standing fluid remained inside the firewall containment area. A small area south of the production equipment does have some overspray, this area will be micro blazed. I will follow up with an initial C-141, if you have any questions please let me know. Thanks

13 barrels of oil was released

9 barrels of PW was released

5 barrels of fluid was recovered by vacuum truck.

Brad Blevins
Assistant Remediation Foreman
BOPCO, LP
522 W. Mermod, Suite 704
Carlsbad, NM 88220
Office-575-887-7329
Cell-1-432-214-3704
bblevins@basspet.com