

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

PAB1435830421 **Release Notification and Corrective Action**
NAB1513851534

OPERATOR Initial Report Final Report

Name of Company OXY USA WTP LP 192463	Contact CAMPBELL, RODNEY
Address 329 Marathon Rd, Lakewood	Telephone No. (575) 628-4167
Facility Name INDIAN BASIN GAS PLANT	Facility Type GAS PROCESSING FACILITY
Surface Owner	Mineral Owner INDIAN BASIN
Lease No.	


LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	23	21-S	23-E					Eddy
				32.4645839		104.5744466		
				Latitude 32°27'52.502" Longitude 104°34'28.004"				

NATURE OF RELEASE

Type of Release Gas	Volume of Release 1982 MCF	Volume Recovered 0
Source of Release Residue Flare	Date and Hour of Occurrence 2/14/2014 11:25:00 AM	Date and Hour of Discovery 2/14/2014 11:25:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? MIKE BRATCHER	
By Whom? RODNEY CAMPBELL	Date and Hour 02/18/2014 12:41 PM LEFT VOICEMAIL	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A	RECEIVED MAR 12 2014 NMOCD ARTESIA	
Describe Cause of Problem and Remedial Action Taken.* Cause: OXY INDIAN BASIN GAS PLANT FLARED RESIDUE SALES GAS AND INLET ENTERPRISE GAS DUE TO HIGH OXYGEN CONTENT. FLARED INTERMITTENTLY FOR FOUR DAYS DUE TO HIGH OXYGEN CONTENT. Remedial Action Taken: OPERATIONS CHECKED STABILIZER DISCHARGE METER WITH PORTABLE OXYGEN ANALYZER BUT DIDN'T SHOW ANYTHING. KINDER MORGAN WAS CALLED OUT TO CHECK THEIR EQUIPMENT, WHICH TESTED OUT GOOD, INDICATING THERE WAS O2 IN GAS STREAM. IT WAS DETERMINED THE SOURCE OF OXYGEN WAS COMING FROM ENTERPRISE GAS. ENTERPRISE GAS COMPRESSORS WERE TAKEN DOWN, AND PIPELINE BLOWN DOWN TO FLARE.		
Describe Area Affected and Cleanup Action Taken.* N/A		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: RODNEY CAMPBELL	Signed By  Approved by District Supervisor:	
Title: HES Specialist	Approval Date: 5/18/15	Expiration Date: N/A
E-mail Address: RODNEY_CAMPBELL@OXY.COM	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: 2-24-14 Phone: (575) 628-4167	SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 6/18/15	

2RP-3007