

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company	Oxy Permian Ltd.	Contact	Chancey Summers
Address	1017 W. Stanolind Rd, Hobbs, NM 88240	Telephone No.	(575) 397-8216
Facility Name	Lost Tank 33 Federal #2	Facility Type	Well location

Surface Owner	BLM	Mineral Owner		API No.	30-015-29330
---------------	-----	---------------	--	---------	--------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	33	21S	31E	330	South	510	West	Eddy

Latitude N 32.42852° Longitude W 103.78965°

**NATURE OF RELEASE**

Type of Release	Produced Water	Volume of Release	2500 bbls	Volume Recovered	20 bbls
Source of Release	Fracture on Y strainer	Date and Hour of Occurrence	07/12/2013	Date and Hour of Discovery	07/12/2013
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-NMOCD; Jennifer Van Curen, James Amos- BLM		
By Whom?	Chancey Summers	Date and Hour	07/15/2013 @ 9:05 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*


Describe Cause of Problem and Remedial Action Taken.\*

A fracture on a Y strainer on a 3" steel pipe from the wellhead to the pump caused 2500 bbls of produced water to leak onto the ground. 20 bbls of water were recovered via vacuum truck and the Y strainer was repaired.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 200' x 175'. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD via email on 10/03/2013 and approved by Jennifer Van Curen of the BLM via email on 09/21/2013.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<u>OIL CONSERVATION DIVISION</u>		
Printed Name: Chancey Summers	Approved by Environmental Specialist:		
Title: HES Specialist	Approval Date: 5/4/15	Expiration Date: N/A	
E-mail Address: Chancey.Summers@oxv.com	Conditions of Approval:	Attached <input type="checkbox"/>	
Date: 11/5/13	Phone: (575) 397-8216	Final	

\* Attach Additional Sheets If Necessary

280-1797