

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB151533420 OPERATOR Initial Report Final Report

Name of Company: Cimarex Energy 11021083	Contact: Gloria Garza
Address: 600 N Marienfeld Ste 600 Midland TX	Telephone No. 432-234-3204
Facility Name: Wersell Federal 1	Facility Type: Tank Battery

Surface Owner: Federal	Mineral Owner	API No. 30-015-20915
------------------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	04	22S	27E	810	FNL	1980	FWL	Eddy

Latitude: 32.42693 Longitude: -104.19662

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 20 BBLs	Volume Recovered: 0 BBLs
Source of Release: Flow line	Date and Hour of Occurrence: 5/28/2015	Date and Hour of Discovery: 5/28/2015
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jeff Robertson BLM & Mike Bratcher OCD	NM OIL CONSERVATION
By Whom? Gloria Garza	Date and Hour: 6/1/2015 4:20 PM CST	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	JUN 1 2015
If a Watercourse was Impacted, Describe Fully.*		RECEIVED
Describe Cause of Problem and Remedial Action Taken.* Corrosion on a 45 pipe fitting attaching two flow lines. Moving forward we will fuse the two flow lines together to eliminate fitting washing out.		
Describe Area Affected and Cleanup Action Taken.* Talon Environmental Services will remediate the impacted soil.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Gloria Garza</i>	OIL CONSERVATION DIVISION	
Printed Name: Gloria Garza	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: ESH Tech	Approval Date: 6/2/15	Expiration Date: N/A
E-mail Address: ggarza@cimarex.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: 6/2/2015 Phone: 432-234-3204	SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: 6/2/15

2RP-3027

Patterson, Heather, EMNRD

From: Gloria Garza <ggarza@cimarex.com>
Sent: Tuesday, June 02, 2015 4:36 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Christine Alderman
Subject: RE: Wersell Federal 1 Spill
Attachments: C-141 Wersell Federal 1 Spill - 5-28-2015.pdf

Here is the C-141 for this spill.

Please call if you have any questions.

Thank you,

Gloria Garza
432.234.3204

From: Gloria Garza
Sent: Monday, June 01, 2015 4:18 PM
To: 'mike.bratcher@state.nm.us'; 'Heather.Patterson@state.nm.us'
Cc: Christine Alderman
Subject: Wersell Federal 1 Spill

Mike/Heather

We had a spill at the Wersell Federal 1 on May 28 due to corrosion on a 45 pipe fitting. The total amount lost was 20 barrels of produced water and 0 barrels were recovered. The leak occurred off of the pad and effected an area approximately 20'X25' .

Moving forward we will well fuse the flow line together so corrosion will not be a problem, C141 to follow.

API # 30-015-20915
04 - 22S - 27E

Please call if you have any questions.

Thank you,

Gloria Garza
ESH Technician
432.234.3204

Patterson, Heather, EMNRD

From: Gloria Garza <ggarza@cimarex.com>
Sent: Monday, June 01, 2015 3:18 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Christine Alderman
Subject: Wersell Federal 1 Spill

Mike/Heather

We had a spill at the Wersell Federal 1 on May 28 due to corrosion on a 45 pipe fitting. The total amount lost was 20 barrels of produced water and 0 barrels were recovered. The leak occurred off of the pad and effected an area approximately 20'X25'.

Moving forward we will well fuse the flow line together so corrosion will not be a problem, C141 to follow.

API # 30-015-20915
04 - 22S - 27E

Please call if you have any questions.

Thank you,

Gloria Garza
ESH Technician
432.234.3204