

# NM OIL CONSERVATION

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

ARTESIA DISTRICT

JUN 12 2015

RECEIVED

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

*NAB1516652299*

OPERATOR

Initial Report  Final Report

Name of Company: BOPCO, L.P. <i>AWD131</i>	Contact: Amy Ruth
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: James Ranch Unit #012H	Facility Type: Production Well
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-22162	

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	21	22S	30E	1450	North	1830	East	Eddy

Latitude 32.380677° Longitude -103.884454°

### NATURE OF RELEASE

Type of Release: Brine Water	Volume of Release: 818 bbls	Volume Recovered: 740 bbls
Source of Release: Jet pump on triplex unit	Date and Hour of Occurrence: 6/8/2015 Time unknown	Date and Hour of Discovery: 6/8/2015 approx. 7 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Heather Patterson (NMOCD) and Jim Amos (BLM)	
By Whom? Tony Savoie	Date and Hour: 9:34 am and 9:37 am respectively <i>6/18/15 @ 9:31am</i>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <i>(according to notification)</i> N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		

Describe Cause of Problem and Remedial Action Taken.\*  
Vibration caused a bolt to shear off of the filter pot lid on the jet pump. Unit was LOTO until repairs can be made. Standing fluids were recovered from the ground and pump containments.

Describe Area Affected and Cleanup Action Taken.\*  
The leak affected 43,350 square feet of well pad and 880 square feet of pasture on the north side of the pad. The impacted area will be delineated and addressed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>[Signature]</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amy Ruth	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Assistant Remediation Foreman	Approval Date: <i>6/15/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: ACRuth@basspet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 6/10/2015	Phone: 432-661-0571	<b>Remediation per O.C.D. Rules &amp; Guidelines</b>

\* Attach Additional Sheets If Necessary

**SUBMIT REMEDIATION PROPOSAL NO LATER THAN:** *7/17/15*

*2RP-3046*

ENVIRONMENTAL RELEASE NOTIFICATION

Call-In Sheet

Date: 6/8/15

Notice received by: MAB

Amy w/ BOPCO 432-661-0571
Name of Company/Phone #

JRU # 12
Facility Name

30-D15-22162
API #

21 228-3DE
Sec. Township Range

6/8/15
Date of Occurrence

6/8/15 @ 9:31am
Date/Hour of Discovery

PW
Type of Release

probably > 25 bbls
Volume of Release

cent
Volume Recovered

Briefly Describe Cause of Problem and action taken:

vibration caused a bolt to shear off the filter
put hidden net pump.

Amy Ruth w/ BOPCO
Notice given by: Name/ Company

6/8/15 9:31 AM
Date/Hour Immediate Notice given

Date C-141 received: 6/12/15

2RP- 3046

\*\*\*\*\*

FLARE NOTIFICATION

Call-In Sheet

Date:

Notice received by:

Name of Company/Phone #

Facility Name

Date of Occurrence

Date/Hour of Flare

Type of Release

Flared MCF Volume

Volume Recovered

Briefly Describe Cause of Problem and action taken:

Notice given by: Name/ Company

Date/Hour Immediate Notice given

Date C-141 received:

2RP-