

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

0AB1517441768 **OPERATOR** Initial Report Final Report

Name of Company: Cimarex Energy <i>215099</i>	Contact: Gloria Garza
Address: 600 N Marienfeld Ste 600 Midland TX	Telephone No. 432-234-3204
Facility Name: Bonnie 35 Federal Com	Facility Type: Tank Battery
Surface Owner: Federal	Mineral Owner
API No.: 30-015-42956	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	35	25S	26E	200	FSL	970	FEL	Eddy

Latitude: 32.0795801765834 Longitude: -104.258295270376

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 15 BBLS	Volume Recovered: 5 BBLS
Source of Release: Water transfer line	Date and Hour of Occurrence: 6/18/2015 7:30 PM	Date and Hour of Discovery: 6/18/2015 7:30 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/Jeff Robertson	
By Whom? Gloria Garza	Date and Hour: 6/19/2015 9:26 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

NM OIL CONSERVATION
ARTESIA DISTRICT
JUN 19 2015

Describe Cause of Problem and Remedial Action Taken.*

A hammer union on the water transfer line came loose due to vibration from pressure.

RECEIVED

Describe Area Affected and Cleanup Action Taken.*

Diversified Environmental Services will remediate the impacted soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Gloria Garza</i>	OIL CONSERVATION DIVISION	
Printed Name: Gloria Garza	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: ESH Tech	Approval Date: <i>6/23/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: ggarza@cimarex.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 6/19/15 Phone: 432-234-3204	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 7/24/15

2RP-3063

Patterson, Heather, EMNRD

From: Gloria Garza <ggarza@cimarex.com>
Sent: Friday, June 19, 2015 3:15 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Christine Alderman
Subject: FW: Bonnie 35 Federal Com Battery Spill - Eddy County - 6/18/2015
Attachments: C-141 Bonnie 35 Federal Com Battery 6-18-15.pdf

Mike/Heather,

Here is the initial C-141 for the spill.

Please call if you have any questions.

Thank you,

Gloria Garza
432.234.3204

From: Gloria Garza
Sent: Friday, June 19, 2015 9:29 AM
To: 'mike.bratcher@state.nm.us'; 'Heather.Patterson@state.nm.us'
Cc: Christine Alderman
Subject: Bonnie 35 Federal Com Battery Spill - Eddy County - 6/18/2015

Good Morning Mike/Heather

We had a spill at the Bonnie 35 Federal Com Battery last night 6/18/2015 due to a hammer union on the water transfer line vibrating loose due to pressure. We had 15 barrels of produce water hit the ground and we were only able to recover 5 barrels of produced water, the fluids were not contained but did stay on location.

API 30-015-42956
Surface Location: P-35-25S-26E 200 FSL 970 FEL
Lat/Long: 32.0795801765834,-104.258295270376

C-141 to follow, please call if you have any questions.

Thank you,

Gloria Garza
ESH Technician
432.234.3204