

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1517555063

OPERATOR

Initial Report Final Report

Name of Company: BOPCO, L.P. 260737	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: JRU #124	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-38113	

LOCATION OF RELEASE

Unit Letter F	Section 17	Township 23S	Range 31E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude: N 32.304969° Longitude: W 103.803745°


NATURE OF RELEASE

Type of Release: produced water	Volume of Release: 11 bbls	Volume Recovered: 10 bbl
Source of Release: water transfer pump connection	Date and Hour of Occurrence: 6/7/15 @ 12:54 pm	Date and Hour of Discovery: 6/7/15 @ 12:54 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	NM OIL CONSERVATION ARTESIA DISTRICT JUN 22 2015
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	
If a Watercourse was Impacted, Describe Fully.* Not Applicable		
RECEIVED		

Describe Cause of Problem and Remedial Action Taken.*
A 1/2" connection on water transfer pump failed releasing produced water to lined containment. Approximately 1 bbl of produced water was released to ground surface between tank containments & south of transfer pump. All remaining fluid remained inside containment area.

Describe Area Affected and Cleanup Action Taken.*
The spill impacted a small area of the tank battery pad between the lined tank containments. Failed connection was replaced and returned transfer pump to normal operations. Vacuum truck and steamer crew were called in to clean liner.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Bradley Blevins	Approved by Environmental Specialist: 	
Title: Assistant Remediation Foreman	Approval Date: 6/24/15	Expiration Date: N/A
E-mail Address: bblevins@basspet.com	Conditions of Approval:	
Date:	Phone: 432-214-3704	Attached <input type="checkbox"/>

Remediation per O.C.D. Rules & Guidelines

**SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 7/30/15**

2RP-3066

* Attach Additional Sheets If Necessary

Patterson, Heather, EMNRD

From: Blevins, Bradley <BBlevins@BassPet.Com>
Sent: Monday, June 22, 2015 8:35 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Savoie, Tony A.; Blevins, Bradley
Subject: Initial C-141 JRU 124
Attachments: Initial C-141 JRU #124.pdf

Mike/ Heather

Please find the attached initial C-141 for the release that occurred at the JRU 124 battery. If you have any questions please let me know. Thank you.

Brad Blevins
Assistant Remediation Foreman
BOPCO, LP
522 W. Mermod, Suite 704
Carlsbad, NM 88220
Office-575-887-7329
Cell-1-432-214-3704
bblevins@basspet.com