

1023 N. FRENCH DR., FLORES, NM 86240
 District II
 811 S. First St., Artesia, NM 88210.
 District III
 1000 Rio Brazos Road, Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

Energy Minerals and Natural Resources

Form C-141
 Revised August 8, 2011

Oil Conservation Division
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
 accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1519640448 **OPERATOR** Initial Report Final Report

Name of Company: BOPCO, L.P. <i>2110737</i>	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: Poker Lake Unit 411H	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner:	API No. 3001539930
------------------------	----------------	-----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	<u>North/South</u> Line	Feet from the	<u>East/West</u> Line	County
B	28	24S	31E	1000		1850		Eddy

Latitude: 32.192796 Longitude: 103.780195

NATURE OF RELEASE

Type of Release: Crude oil, Produced water	Volume of Release: 3 barrels oil, 11 barrels produced water	Volume Recovered: 1 barrel oil, 0 produced water recovered
Source of Release: Sight glass failure	Date and Hour of Occurrence: July 2, 2015 @ 6:00pm	Date and Hour of Discovery: July 2, 2015 @ 6:28pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

NM OIL CONSERVATION

If a Watercourse was Impacted, Describe Fully.*

ARTESIA DISTRICT
JUL 10 2015

RECEIVED

Describe Cause of Problem and Remedial Action Taken.*
 Release of oil and produced water occurred at the FWKO due to a failed sight glass. Affected well pad around production equipment, all fluid was contained within earth berm.

Describe Area Affected and Cleanup Action Taken.*
 A vacuum truck was called to the location and was able to recover 1 barrel of oil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bradley Blevins</i>	OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins	Approved by Environmental Specialist: <i>M. L. Blevins</i>	
Title: Assistant Remediation Foreman	Approval Date: <i>7/14/15</i>	Expiration Date: <i>NIA</i>
E-mail Address: bblevins@basspet.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines	
Date: <i>7-10-15</i> Phone: 432-214-3704	Attached <input type="checkbox"/>	

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 7/14/15

* Attach Additional Sheets If Necessary

2RP-3107

Bratcher, Mike, EMNRD

From: Blevins, Bradley <BBlevins@BassPet.Com>
Sent: Friday, July 10, 2015 12:52 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Blevins, Bradley
Subject: Initial C-141 PLU 411H
Attachments: doc04421620150710112249.pdf

Mike/ Heather

Please find the attached initial C-141 for the PLU 411H, if you have any questions please let me know. Thank you.

Brad Blevins
Assistant Remediation Foreman
BOPCO, LP
522 W. Mermod, Suite 704
Carlsbad, NM 88220
Office-575-887-7329
Cell-1-432-214-3704
bblevins@basspet.com

Patterson, Heather, EMNRD

From: Ruth, Amy C. <ACRuth@BassPet.Com>
Sent: Friday, July 03, 2015 9:14 AM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD
Subject: BOPCO PLU 411 leak 7-2-15
Attachments: image1.jpeg

Leak was discovered late yesterday afternoon. It looks to be less than 25 bbls though more than 5. I will calculate oil/pw totals and submit C-141. Have a good 4th!!!

- >
- > The following Wellsite information and coordinates have been shared with you via Wellsite Navigator Pro iOS Edition.
- >
- > Name: poker lake unit 411h bopco l.p.
- > Description: API: 3001539930
- > Latitude: 32.192796
- > Longitude: -103.780195
- >
- > See a Map of this Well<<http://maps.google.com/maps?saddr=&daddr=32.192796,-103.780195>>
- >
- > [image1.jpeg]
- > Pumper reported spill due to sight glass broken on FWKO. Vac truck recovered 1 bbl total fluid. Gang replaced broken sight glass.
- >
- > Sent from my iPhone