

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1522939771

Name of Company Oxy Permian Ltd. 192403		Contact CJ Summers	<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Address 6 Desta Drive, Midland, TX 79705		Telephone No. (432) 685-5824		
Facility Name Cougar Fed Com #1 Battery		Facility Type Battery		
Surface Owner BLM	Mineral Owner	API No. 30-015-29950		

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	35	18S	29E					Eddy County, NM

Latitude N 32.70858° Longitude W 104.04045°

NATURE OF RELEASE

Type of Release Oil and produced water	Volume of Release 50 bbls oil, 25 bbls produced water	Volume Recovered 0 bbls
Source of Release Internal corrosion of the central oil tank	Date and Hour of Occurrence 07/28/2015	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher and Heather Patterson-NMOCD, Shelly Tucker-BLM	
By Whom? Kathy Purvis @ BBC International Inc.	Date and Hour 07/28/2015 @ 3:07 pm	NM OIL CONSERVATION ARTESIA DISTRICT AUG 14 2015 RECEIVED
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

Internal corrosion of the central oil tank caused 50 bbls of oil and 25 bbls of produced water onto the ground. The fluids were not recoverable and the tank was repaired or removed.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 75' x 35' on location inside the firewall. Remediation will be completed according to a remediation plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: CJ Summers	Approved by Environmental Specialist: 	
Title: HES Lead	Approval Date: 8/17/15	Expiration Date: N/A
E-mail Address: chancey_summers@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 8-13-15 Phone: (432) 685-5824	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 9/18/15

2RP-3202

Patterson, Heather, EMNRD

From: Kathy Purvis <kathy@bbcinternational.com>
Sent: Friday, August 14, 2015 4:28 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; stucker@blm.gov; jamos@blm.gov
Cc: C J Summers; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; jgilkey@bbcinternational.com
Subject: Initial C-141, Cougar Fed Com #1 Battery
Attachments: Initial C-141, Cougar Fed Com #1 Battery.pdf

Attached is the initial C-141 for a leak that occurred at the Cougar Fed Com #1 Battery on 07/28/2015 in Eddy County, NM. Receipt notification via email is greatly appreciated.

Kathy Purvis

BBC International, Inc.
1324 W. Marland
Hobbs, NM 88240
Phone: (575) 397-6388
Fax: (575) 397-0397
Email: kathy@bbcinternational.com

Bratcher, Mike, EMNRD

From: Kathy Purvis <kathy@bbcinternational.com>
Sent: Tuesday, July 28, 2015 3:07 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; stucker@blm.gov
Cc: C J Summers; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; jgilkey@bbcinternational.com; Kathy Purvis
Subject: Cougar Fed Com #1 Battery

This is to inform you that Oxy Permian had a leak at the Cougar Fed Com #1 Battery on July 28, 2015. Oxy spilled 50 bbls of oil and 25 bbls of produced water due to internal corrosion on the central oil tank. The preliminary report shows the leak measuring approximately 20' x 100' on location. The fluids were not recoverable. The release is located in the NE ¼ of Section 35, T18S, R29E of Eddy County, NM. BBC International will remediate the location at a later date and an initial C-141 will follow. Driving directions: From Carlsbad, go east on the Hobbs Hwy, turn north on NM360 and go to mile marker 15, turn left and go 0.25 mile to location at the end of the road. API# 30-15-29950, GPS coordinates are not available at this time.

Kathy Purvis

BBC International, Inc.
1324 W. Marland
Hobbs, NM 88240
Phone: (575) 397-6388
Fax: (575) 397-0397
Email: kathy@bbcinternational.com