

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1523233540 OPERATOR Initial Report Final Report

Name of Company: BOPCO, L.P. <u>2100731</u>	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU CVX JV BS 006H <u>Big Sinks 2</u>	Facility Type: Exploration and Production
Surface Owner: State	Mineral Owner: <u>24 30 STATE # 2H</u>
API No. 3001542496	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	2	24S	30E	2500		330		Eddy

Latitude: 32.24762 Longitude: 103.85899

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 35 barrels	Volume Recovered: 30 barrels
Source of Release: ¼ inch high pressure hose	Date and Hour of Occurrence: 8-13-15 @ 11:45am	Date and Hour of Discovery: 8-13-15 @ 12:10pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, Heather Patterson, Jim Amos via email	
By Whom? Bradley Blevins	Date and Hour 8-13-15 @ 3:10pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

NM OIL CONSERVATION
ARTESIA DISTRICT
AUG 14 2015

RECEIVED

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A ¼ inch high pressure hose failed on murphy kill. 35 barrels of produced water was released, 30 barrels being inside the lined containment. The fluid inside the containment was recovered via vacuum truck. The high pressure hose was replaced.

Describe Area Affected and Cleanup Action Taken.*

A vacuum truck was called to the location and was able to recover 30 barrels PW from inside the lined containment. The ¼ inch hose was replaced.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <u>Bradley Blevins</u>	Approved by Environmental Specialist: <u>[Signature]</u>	
Printed Name: Bradley Blevins	Approval Date: <u>8/17/15</u>	Expiration Date: <u>N/A</u>
Title: Assistant Remediation Foreman	Conditions of Approval:	
E-mail Address: bblevins@basspet.com	Attached <input type="checkbox"/>	
Date: <u>8-14-15</u> Phone: 432-214-3704	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 9/21/15

2RP-3215

Patterson, Heather, EMNRD

From: Blevins, Bradley <BBlevins@BassPet.Com>
Sent: Friday, August 14, 2015 11:59 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Amos, James
Cc: Blevins, Bradley
Subject: Initial C-141 PLU CVX JV BS 006H
Attachments: doc04502820150814105620.pdf

All,

Please find the attached initial C-141 for the PLU CVX JV BS 006H, if you have any questions please let me know.
Thank you

Brad Blevins
Remediation Foreman (PLU)
BOPCO, LP
522 W. Mermod, Suite 704
Carlsbad, NM 88220
Office-575-887-7329
Cell-1-432-214-3704
bblevins@basspet.com

Bratcher, Mike, EMNRD

From: Blevins, Bradley <BBlevins@BassPet.Com>
Sent: Thursday, August 13, 2015 3:10 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Jim Amos
Cc: Blevins, Bradley
Subject: PLU CVX JV BS 006H Release

All,
BOPCO EHS was notified of a release that occurred at the PLU CVX JV BS 006H. A 1/4 inch HP kill switch hose failed and released PW into the lined containment, 4.77 barrels PW was calculated out side of containment. 30 barrels PW was recovered from the lined containment. The hose has been replaced.
Thanks

Sent from my iPhone

Bustamante, Amalia, EMNRD

From: Patterson, Heather, EMNRD
Sent: Wednesday, August 19, 2015 4:33 PM
To: Bustamante, Amalia, EMNRD
Subject: Fwd: RE: Initial C-141 PLU CVX JV BS 006H

Sent from my Verizon Wireless 4G LTE DROID

----- Forwarded message -----

From: "Blevins, Bradley" <BBlevins@BassPet.Com>
Date: Aug 19, 2015 9:59 AM
Subject: RE: Initial C-141 PLU CVX JV BS 006H
To: "Patterson, Heather, EMNRD" <Heather.Patterson@state.nm.us>
Cc:

Heather,

I apologize for the misunderstanding. Below is the well information, I thought the new well name was the PLU CVX JV BS 006H.

API Number: 3001542456
ULSTR: E-2-24S-30E
Footages 2500 FNL & 330 FWL
Well Name & Number: BIG SINKS 2 24 30 STATE No. 002H
Operator: BOPCO, L.P.

From: Patterson, Heather, EMNRD [mailto:Heather.Patterson@state.nm.us]
Sent: Tuesday, August 18, 2015 10:39 AM
To: Blevins, Bradley
Subject: RE: Initial C-141 PLU CVX JV BS 006H

Bradley,

Can you double check the API and well name on this C-141?

Heather Patterson
Environmental Specialist
NMOCD District II
Office (575)748-1283 ext.101
Cell (575)703-0228

From: Blevins, Bradley [mailto:BBlevins@BassPet.Com]
Sent: Friday, August 14, 2015 11:59 AM