

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB152442A236

Name of Company: COG Operating LLC 229137		OPERATOR	<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Address: 600 West Illinois Avenue, Midland TX 79701		Contact: Robert McNeill		
Facility Name: Harper State #9		Telephone No. 432-230-0077		
		Facility Type: Well		
Surface Owner: State		Mineral Owner:	API No. 30-015-34869	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	16	17S	30E	2310'	South	330'	East	Eddy

Latitude 32.8336678 Longitude -103.9695129

NATURE OF RELEASE

Type of Release: Oil & Produced Water	Volume of Release: 5 bbls Oil ; 15 bbls PW	Volume Recovered: 4 bbls Oil ; 14 bbls PW
Source of Release: Flowline	Date and Hour of Occurrence: 8/2/2015 9:00 am	Date and Hour of Discovery: 8/2/2015 9:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? NM OIL CONSERVATION	
By Whom?	Date and Hour: ARTESIA DISTRICT	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. AUG 28 2015	

If a Watercourse was Impacted, Describe Fully.*
RECEIVED

Describe Cause of Problem and Remedial Action Taken.*
This release was caused by a corroded flowline. A vacuum truck was dispatched to recover all standing fluids and repairs were made to the flowline.

Describe Area Affected and Cleanup Action Taken.*
This release occurred in the pasture. Standing fluids were recovered and a treatment of Microblaze applied. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist:	
Title: Senior Environmental Coordinator	Approval Date: 9/1/15	Expiration Date: N/A
E-mail Address: atrujillo@concho.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines	
Date: 8/16/2015 Phone: 575-748-6940	Attached <input type="checkbox"/> SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: 10/2/15 **2RP-3229**

Patterson, Heather, EMNRD

From: Amanda Trujillo <ATrujillo@concho.com>
Sent: Friday, August 28, 2015 9:03 PM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD
Subject: (Notification/C-141 Initial) Harper State #9 (30-015-34869)
Attachments: 8-2-2015 Harper State #9 (FL) Initial.pdf

Mr. Bratcher,

COG Operating LLC is reporting a release on the Harper State #9 (30-015-34869)
Unit I Section 16 Township 17S Range 30E
The release occurred at 9:00 am 8/2/2015
Released: 5 bbls Oil; 15 bbls PW
Recovered: 4 bbls Oil; 14 bbls PW

This released was caused by a corroded flowline. Attached is a C-141 Initial for your consideration. If you have any additional questions please feel free to contact me.

Thank you,

Amanda Trujillo

Senior Environmental Coordinator
COG Operating LLC
Cell: 505.350.1336
Office: 575.748.6930
atrujillo@concho.com

2407 Pecos Ave.
Artesia , NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.