

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

*NAB1528133563*

**OPERATOR**  Initial Report  Final Report

Name of Company	Burnett Oil Co., Inc. <i>3080</i>	Contact	Leslie Garvis
Address	801 Cherry Street, Ste 1500, Ft. Worth, TX 76102	Telephone No.	817-583-8730
Facility Name	Gissler B 31	Facility Type	Oil Well
Surface Owner	BLM	Mineral Owner	BLM
		API No.	30-015-32200

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	14	17S	30E	1650	South	990	West	Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release	Oil/produced water	Volume of Release 2 bbls/30 bbls	Volume Recovered	0
Source of Release	Steel flowline corroded and ruptured	Date and Hour of Occurrence	Date and Hour of Discovery 9/30/15 0800	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? VMail & Email - H.Patterson, OCD & J.Amos, BLM		
By Whom?	Leslie Garvis	Date and Hour	10/1/15 12:50	
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.		

If a Watercourse was Impacted, Describe Fully.\*

N/A

Describe Cause of Problem and Remedial Action Taken.\*

Steel Flowline from the GJSAU 22 WIW (API #30-15-04148) corroded and ruptured at the Gissler B 31 site.

Describe Area Affected and Cleanup Action Taken.\*

Release occurred on the pad and flowed into the nearby pasture. An area of approximately 100'x5' was affected in the pasture. Area will be assessed and remediated per regulatory standards. Clean up plan will be submitted by BOCI - J. Titsworth.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Leslie Garvis</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Leslie Garvis	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Regulatory Coordinator	Approval Date: <i>10/8/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: lgarvis@burnettoil.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10/7/15	Phone: 817-583-8730	

**Remediation per O.C.D. Rules & Guidelines**  
**SUBMIT REMEDIATION PROPOSAL NO**  
**LATER THAN: *11/8/15***

*2RP-5320*

\* Attach Additional Sheets If Necessary

**Patterson, Heather, EMNRD**

---

**From:** Leslie Garvis <lgarvis@burnettoil.com>  
**Sent:** Wednesday, October 07, 2015 2:25 PM  
**To:** 'Amos, James'; Patterson, Heather, EMNRD; stucker@blm.gov  
**Cc:** Walter Glasgow; Brady Sullivan; Trey Krampf; Belton Mathews; Kenny Palmer; Charlie Smitherman; Kyle Adams; Johnny Titsworth  
**Subject:** RE: Release at the Gissler B 31- API# 30-015-32200  
**Attachments:** 2015.10.07 GB 31 C141\_Initial.pdf

Attached you will find the initial C-141 for this release. Johnny Titsworth will be working on the remediation plan and we will get it to you as soon as possible..

If you have any questions, please let me know.

Thank you,

**LESLIE M. GARVIS**  
REGULATORY COORDINATOR

**BURNETT OIL Co., INC.**  
BURNETT PLAZA-SUITE 1500  
801 CHERRY STREET - UNIT #9  
FORT WORTH, TX 76102-6881  
DIRECT LINE: 817.583.8730  
MOBILE: 713.819.4371  
FAX: (817) 332-2438  
EMAIL: LGARVIS@BURNETTOIL.COM

---

**From:** Leslie Garvis  
**Sent:** Wednesday, September 30, 2015 12:29 PM  
**To:** Amos, James; Heather.Patterson@state.nm.us  
**Cc:** Walter Glasgow; Brady Sullivan; Trey Krampf; Belton Mathews; Kenny Palmer (Kpalmer@burnettoil.com); Charlie Smitherman; Kyle Adams (KAdams@burnettoil.com)  
**Subject:** Release at the Gissler B 31- API# 30-015-32200

Jim/Heather,

To follow up on the voice mail that I just left you both, we had a GJSAU injection line rupture at the Gissler B 31 location. The spill originated on the pad and flowed off location into the nearby pasture. The size of the area impacted is approximately 80-100 feet long and between 2-5 feet wide.

Once I have further details, I will submit the initial C-141.

Thank you.

**LESLIE M. GARVIS**  
REGULATORY COORDINATOR

**BURNETT OIL Co., INC.**  
BURNETT PLAZA-SUITE 1500  
801 CHERRY STREET - UNIT #9

FORT WORTH, TX 76102-6881  
DIRECT LINE: 817.583.8730  
MOBILE: 713.819.4371  
FAX: (817) 332-2438  
EMAIL: [LGARVIS@BURNETTOIL.COM](mailto:LGARVIS@BURNETTOIL.COM)

This message is intended only for the person(s) to which it is addressed and may contain privileged, confidential and/or insider information. If you have received this communication in error, please notify us immediately by replying to the message and deleting it from your computer. Any disclosure, copying, distribution, or the taking of any action concerning the contents of this message and any attachment(s) by anyone other than the named recipient(s) is strictly prohibited.

## **Patterson, Heather, EMNRD**

---

**From:** Leslie Garvis <lgarvis@burnettoil.com>  
**Sent:** Wednesday, September 30, 2015 11:29 AM  
**To:** Amos, James; Patterson, Heather, EMNRD  
**Cc:** Walter Glasgow; Brady Sullivan; Trey Krampf; Belton Mathews; Kenny Palmer; Charlie Smitherman; Kyle Adams  
**Subject:** Release at the Gissler B 31- API# 30-015-32200

**Categories:** printed

Jim/Heather,

To follow up on the voice mail that I just left you both, we had a GJSAU injection line rupture at the Gissler B 31 location. The spill originated on the pad and flowed off location into the nearby pasture. The size of the area impacted is approximately 80-100 feet long and between 2-5 feet wide.

Once I have further details, I will submit the initial C-141.

Thank you.

**LESLIE M. GARVIS**  
REGULATORY COORDINATOR

**BURNETT OIL CO., INC.**  
BURNETT PLAZA-SUITE 1500  
801 CHERRY STREET - UNIT #9  
FORT WORTH, TX 76102-6881  
DIRECT LINE: 817.583.8730  
MOBILE: 713.819.4371  
FAX: (817) 332-2438  
EMAIL: LGARVIS@BURNETTOIL.COM

This message is intended only for the person(s) to which it is addressed and may contain privileged, confidential and/or insider information. If you have received this communication in error, please notify us immediately by replying to the message and deleting it from your computer. Any disclosure, copying, distribution, or the taking of any action concerning the contents of this message and any attachment(s) by anyone other than the named recipient(s) is strictly prohibited.