

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

NOV 11 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1532034732

OPERATOR

Initial Report Final Report

Name of Company	Southwest Royalties 257010	Contact	Luis Gonzalez
Address	6-Desta Drive Suite 1100 Midland, Tx 79705	Telephone No.	(432) 661-4708
Facility Name	State 20 E #1 Clayton Williams Energy, Inc.	Facility Type	Oil Well
Surface Owner	State of NM	Mineral Owner	State of NM
		API No.	30-015-30969

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	20	17S	29E					Eddy

Latitude 32°49'26.30 Longitude 104°05'30.92

NATURE OF RELEASE

Type of Release	Oil/Produced Water	Volume of Release	35	Volume Recovered	30
Source of Release	Flowline Leak	Date and Hour of Occurrence	11/09/15	Date and Hour of Discovery	11/09/15
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	Left a voicemail for Heather Patterson 11/10/15 @ 2:44pm <i>(HP)</i>		
By Whom?	Eric Garcia	Date and Hour	11/10/2015		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Flowline leak. Crew was called out to repair the leak. Also, crew put up a fence around the spill area. Vacuum truck picked up approx. 30 barrels of oil. One call was made.

Describe Area Affected and Cleanup Action Taken.*
The area affected is pasture. The spill measure approx. 60' X10'. Crew put up a fence to prevent cattle from entering and a One Call was performed. Once the One Call clears the area will be cleaned up in accordance of NMOCD Guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Dave Dunlap</i>	OIL CONSERVATION DIVISION	
Printed Name: DAVE DUNLAP	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Prod Foreman	Approval Date: 11/7/15	Expiration Date: N/A
E-mail Address: ddunlap@claytonwilliams.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/>	
Date: 11-10-15 Phone: 525 390 2062	SUBMIT REMEDIATION PROPOSAL NO LATER THAN: <u>12/17/15</u>	

* Attach Additional Sheets If Necessary

2RP-3305

Patterson, Heather, EMNRD

From: eric garcia <ericgarcia62@hotmail.com>
Sent: Wednesday, November 11, 2015 11:04 AM
To: Patterson, Heather, EMNRD; lgonzalez@claytonwilliams.com; eric garcia
Subject: State 20 E #1 C-141
Attachments: Clayton Williams Inc-C 141.jpeg

Heather,

My name is Eric Garcia with Republic Backhoe Service LLC. On 11/09/2015 I received a phone call from Dave Dunlap field supervisor for Clayton Williams Inc. He mentioned that there was a flow line leak at the State 20 E #1. I went to the location to begin the clean up process. A vacuum truck was sent out to the location to the remove standing fluids in the pasture. Approx 30 barrels of oil were recovered. A one call was performed and as fence was put up around the spill area to prevent cattle from entering. The following attachment contains the Release Notification for the State 20 E #1. If you have any questions please call me at (575) 631-0131.

Eric Garcia

Republic Backhoe Service LLC

sent email
about why Southern
Royalties is listed
as the
company
not Clayton Williams