

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

DEC 08 2015

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED** to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

*NAB1534455140*

Name of Company: BOPCO, L.P. <i>8100737</i>	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU 151	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner:
API No. 3001531595	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	6	24s	30E	510		1980		Eddy

Latitude: 32.25264 Longitude: 103.91865

**NATURE OF RELEASE**

Type of Release: Produced Water	Volume of Release: 7 barrels PW	Volume Recovered: None
Source of Release: Corrosion to 2x1 swedge	Date and Hour of Occurrence: 12-7-15 @ 3:00pm	Date and Hour of Discovery: 12-7-15 @ 3:38pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
BOPCO EHS was notified of a release that occurred when a hole developed in a 2x1 swedge caused by corrosion. A vacuum truck was called but no fluid was able to be recovered. The majority of the fluid stayed on the well pad with the exception of 1.1 barrels ran off the north side of the pad.

Describe Area Affected and Cleanup Action Taken.\*  
A vacuum truck was called but no fluid was able to be recovered. The majority of the fluid stayed on the well pad with the exception of 1.1 barrels ran off the north side of the pad. The failed swedge and connections were replaced with HP stainless steel.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bradley Blevins</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Bradley Blevins	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Assistant Remediation Foreman	Approval Date: <i>12/10/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: bblevins@basspet.com	Conditions of Approval: <b>Remediation per O.C.D. Rules &amp; Guidelines</b> Attached <input type="checkbox"/>	
Date: <i>12-8-15</i> Phone: 432-214-3704	<b>SUBMIT REMEDIATION PROPOSAL NO</b>	

\* Attach Additional Sheets If Necessary

LATER THAN: *1/15/16*

*2RP-3439*

## Bratcher, Mike, EMNRD

---

**From:** Blevins, Bradley <BBlevins@BassPet.Com>  
**Sent:** Tuesday, December 08, 2015 2:31 PM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Amos, James  
**Cc:** Blevins, Bradley  
**Subject:** Initial C-141 PLU 151  
**Attachments:** Initial C-141 PLU 151.pdf

All,  
Please find the attached initial C-141 for the release that occurred at the PLU 151. If you have any questions please let me know.  
Thanks,

Brad Blevins  
Remediation Foreman  
BOPCO, LP  
522 W. Mermod, Suite 704  
Carlsbad, NM 88220  
Office-575-887-7329  
Cell-1-432-214-3704  
bblevins@basspet.com