

NM OIL CONSERVATION

ARTESIA DISTRICT

DEC 09 2015

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

RECEIVED

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1534548986

OPERATOR

Initial Report Final Report

Name of Company	Oxy Permian Ltd. <i>11010910</i>	Contact	Dusty Wilson
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	432-685-5771
Facility Name	Cedar Canyon 16 State #8H	Facility Type	Well

Surface Owner	State	Mineral Owner	API No. 30-015-41596
---------------	-------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	16	24S	29E					Eddy

Latitude N 32.22223° Longitude N 103.98106°

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	5 bbls oil, 40 bbls produced water	Volume Recovered	0 bbls
Source of Release	Discharge fire on suction line	Date and Hour of Occurrence	11/11/15	Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Heather Patterson, Mike Bratcher		
By Whom?	Kathy Purvis @ BBC International	Date and Hour	11/16/15 @ 11:53 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
A static discharge fire on the gas compressor suction line caused 5 bbls of oil and 40 bbls of produced water to leak onto the ground. No fluids were recovered and the line was repaired/replaced.

Describe Area Affected and Cleanup Action Taken.*
The affected area is approximately 55' x 80' off location near the trench. Remediation will be completed in accordance with the remediation plan approved by NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>[Signature]</i>	OIL CONSERVATION DIVISION	
Printed Name:	Casey Summers	Approved by Environmental Specialist:	<i>[Signature]</i>
Title:	NM Environmental Advisor	Approval Date:	12/10/15
E-mail Address:	casey_summers@oxy.com	Expiration Date:	N/A
Date:	12-9-15	Phone:	(575)513-8289

Conditions of Approval:
Remediation per O.C.D. Rules & Guidelines
SUBMIT REMEDIATION PROPOSAL NO

LATER THAN: 11/5/16 2RP 341

* Attach Additional Sheets If Necessary

Bratcher, Mike, EMNRD

From: Kathy Purvis <kathy@bbcinternational.com>
Sent: Wednesday, December 09, 2015 2:31 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: dusty_wilson@oxy.com; frank_barnett@oxy.com; Casey_Summers@oxy.com; Jennifer_duarte@oxy.com; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; jgilkey@bbcinternational.com
Subject: Initial C-141, Cedar Canyon 16 State #8H
Attachments: Initial C-141, Cedar Canyon 16 State #8H.pdf

Attached is the initial C-141 for a leak that occurred at the Cedar Canyon 16 State #8H on 11/11/2015 in Eddy County, NM. Receipt notification via email is greatly appreciated.

Kathy Purvis

BBC International, Inc.
1324 W. Marland
Hobbs, NM 88240
Phone: (575) 397-6388
Fax: (575) 397-0397
Email: kathy@bbcinternational.com

Bratcher, Mike, EMNRD

From: Kathy Purvis <kathy@bbcinternational.com>
Sent: Monday, November 16, 2015 11:53 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: dusty_wilson@oxy.com; frank_barnett@oxy.com; Jennifer_duarte@oxy.com; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; jgilkey@bbcinternational.com; kathy@bbcinternational.com
Subject: Cedar Canyon 16 State #8H

This is to inform you that Oxy Permian had a leak at the Cedar Canyon 16 State #8H on November 11, 2015. Oxy spilled 5 bbls of oil and 40 bbls of water due to a static discharge fire on the gas compressor suction line. The preliminary report shows the leak measuring approximately 200' x 100' off location approximately 150' east of the well. No fluids were recovered. The release is located east of U/L A of Section 16, T24S, R29E of Eddy County, NM. BBC International will remediate the location at a later date and an initial C-141 will follow. Driving directions: From Carlsbad, go south on US285 to Malaga, turn left on Duarte Rd, turn right on McDonald Rd, turn left on Dogtown Rd, cross the river, turn left and follow road to 3rd right that lead to the location. API# 30-015-41596 GPS coordinates are not available at this time.

Kathy Purvis

BBC International, Inc.
1324 W. Marland
Hobbs, NM 88240
Phone: (575) 397-6388
Fax: (575) 397-0397
Email: kathy@bbcinternational.com