

NM OIL CONSERVATION

ARTESIA DISTRICT

DEC 30 2015

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

RECEIVED
Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1536455073

OPERATOR Initial Report Final Report

Name of Company	Oxy Permian Ltd. 192463	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	Winston SWD #004	Facility Type	Intake line
Surface Owner	BLM	Mineral Owner	API No. 30-15-30337

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	31	21S	24E					Eddy County, NM

Latitude N 32.43829° Longitude W 104.54519°

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	11 bbls	Volume Recovered	0 bbls
Source of Release	Corrosion of an intake pipe in the pump building	Date and Hour of Occurrence	12/04/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Heather Patterson-NMOCD; Shelly Tucker-BLM		
By Whom?	Kathy Purvis @ BBC International	Date and Hour	12/11/2015 @ 11:57 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Corrosion of an intake pipe in the pump building caused 11 bbls of produced water to leak onto the ground. No fluids were recovered and the pipe was repaired or replaced.

Describe Area Affected and Cleanup Action Taken.*
The affected area is approximately 62' x 50' inside the pump building. Remediation will be completed in accordance with a remediation plan approved by both NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:		Approved by Environmental Specialist:	
Printed Name:	Casey Summers	Approval Date:	12/30/15
Title:	NM Environmental Advisor	Expiration Date:	NA
E-mail Address:	Casey.Summers@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date:	12-28-15	Phone:	(575) 513-8289

Remediation per O.C.D. Rules & Guidelines
SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 1/31/16

2RP-3469

* Attach Additional Sheets If Necessary

Patterson, Heather, EMNRD

From: Kathy Purvis <kathy@bbcinternational.com>
Sent: Wednesday, December 30, 2015 10:09 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; stucker@blm.gov
Cc: Casey_Summers@oxy.com; dusty_wilson@oxy.com; Jennifer_duarte@oxy.com; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; jgilkey@bbcinternational.com
Subject: Initial C-141, Winston SWD #004
Attachments: Initial C-141, Winston SWD #004.pdf

Attached is the initial C-141 for a leak that occurred at the Winston SWD #004 on 12/04/2015 in Eddy County, NM. Receipt notification via email is greatly appreciated.

Kathy Purvis

BBC International, Inc.
1324 W. Marland
Hobbs, NM 88240
Phone: (575) 397-6388
Fax: (575) 397-0397
Email: kathy@bbcinternational.com

Bratcher, Mike, EMNRD

From: Kathy Purvis <kathy@bbcinternational.com>
Sent: Friday, December 11, 2015 11:57 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; stucker@blm.gov
Cc: dusty_wilson@oxy.com; Jennifer_duarte@oxy.com; frank_barnett@oxy.com;
cbrunson@bbcinternational.com; kswinney@bbcinternational.com;
jgilkey@bbcinternational.com; kathy@bbcinternational.com
Subject: Winston SWD #004

This is to inform you that Oxy Permian had a leak at the Winston SWD #004 on December 4, 2015. Oxy spilled 11 bbls of produced water due to internal corrosion of an intake pipe in the H-pump Bldg. The preliminary report shows the leak measuring approximately 60' x 40' on location. No fluids were recovered. The release is located in U/L E of Section 31, T21S, R24E of Eddy County, NM. BBC International will remediate the location at a later date and an initial C-141 will follow. Driving directions: From Carlsbad, go north on US285 to NM137, turn left at mile marker 44, take a right, then stay left as the road forks; facility is on the left. API# 30-015-30337 GPS coordinates: N 32.43822° N 104.54510°

Kathy Purvis

BBC International, Inc.
1324 W. Marland
Hobbs, NM 88240
Phone: (575) 397-6388
Fax: (575) 397-0397
Email: kathy@bbcinternational.com