

NM OIL CONSERVATION
ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

JAN 19 2016

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1102154004

OPERATOR

Initial Report Final Report

Name of Company Yates Petroleum Corporation	Contact Robert Asher
Address 104 S. 4 th Street	Telephone No. 575-748-4217
Facility Name Juniper BIP Federal #9H	Facility Type Pumping Unit

Surface Owner Federal	Mineral Owner Federal	API No. 30-015-37407
--------------------------	--------------------------	-------------------------

LOCATION OF RELEASE

Unit Letter M	Section 4	Township 24S	Range 29E	Feet from the 130	North/South Line South	Feet from the 330	East/West Line East	County Eddy
------------------	--------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.23981 Longitude 103.99604

NATURE OF RELEASE

Type of Release Crude Oil & Produced Water	Volume of Release 2.5 B/O & 2.5 B/PW	Volume Recovered 0 B/O & 0 B/PW
Source of Release Pumping Unit	Date and Hour of Occurrence 10/11/2015; AM	Date and Hour of Discovery 10/11/2015; AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

The flow line from the well head developed a hole and caused the release. The well was shut off and vacuum truck(s) were called.

Describe Area Affected and Cleanup Action Taken.*

An approximate area of 20' x 20' and remained on the well pad. Vacuum truck(s) recovered none of the released oil and produced water. The impacted soils were excavated and hauled to an NMOCD approved facility and Micro Blaze was applied to the release area. **Depth to Ground Water: 50-90' (approximately 65', per ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: > 1000', SITE RANKING IS 10. Based on the small amounts release, all impacted soils were excavated/hauled and Micro Blaze applied to the affected area, Yates Petroleum Corporation requests closure.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Signed By  Approved by Environmental Specialist:	
Title: NM Environmental Regulatory Supervisor	Approval Date: <u>11/21/16</u>	Expiration Date: <u>N/A</u>
E-mail Address: boba@yatespetroleum.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: 1/19/2016	Phone: 575-748-4217	2RP-

* Attach Additional Sheets If Necessary

2RP-3505

Bratcher, Mike, EMNRD

From: Bob Asher <BobA@yatespetroleum.com>
Sent: Tuesday, January 19, 2016 11:53 AM
To: Bratcher, Mike, EMNRD
Subject: C-141, Initial/Final Report (Juniper BPI Federal #9H)
Attachments: Juniper BIP Federal 9H.pdf

Thank you.

Robert Asher
NM Environmental Regulatory Supervisor
Yates Petroleum Corporation
105 S. 4th Street
Artesia, NM 88210
575-748-4217 (Office)
575-365-4021 (Cell)

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.

Bratcher, Mike, EMNRD

From: Bob Asher <BobA@yatespetroleum.com>
Sent: Tuesday, January 19, 2016 11:43 AM
To: Bratcher, Mike, EMNRD
Subject: Form C-141 Initial/Final Reports

Mike,

I was looking through our files and then on OCD Online, it appears that there was two (2) releases that occurred on Yates facilities where a C-141 was not submitted. The releases occurred during the time frame a few months back during the last layoff period and the tech submitting the C-141's was no longer with our group. I will submit each report separately (listed below).

Doc BHU State #1
Juniper BIP Federal #9H

Contact me if there are any questions.

Thank you.

Robert Asher
NM Environmental Regulatory Supervisor
Yates Petroleum Corporation
105 S. 4th Street
Artesia, NM 88210
575-748-4217 (Office)
575-365-4021 (Cell)

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.
