

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

JAN 21 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1602156653 OPERATOR Initial Report Final Report

Name of Company *Burnett Oil Co., Inc.* *3080* Contact *Leslie Garvis*

Address *Burnett Plaza - Suite 1500, 801 Cherry Street-Unit 9, Ft. Worth, TX 76102* Telephone No. *817-583-8730*

Facility Name *Jackson B 6* ✓ Facility Type *Tank Battery*

Surface Owner *BLM* Mineral Owner *BLM* API No. *30-015-31333*

NOT CORRECT API#

LOCATION OF RELEASE

Unit Letter H	Section 24	Township 17S	Range 30E	Feet from the 2310	North/South Line North	Feet from the 380	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	----------------

30-015-04326

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release <i>Oil</i>	Volume of Release <i>10 gallons</i>	Volume Recovered <i>0</i>
Source of Release <i>Fire at Heater Treater</i>	Date and Hour of Occurrence <i>1/13/2016 1520</i>	Date and Hour of Discovery <i>1/13/2016 1520</i>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <i>BLM - S.Tucker, OCD - H.Patterson</i>	
By Whom? <i>Leslie Garvis</i>	Date and Hour <i>Call - 1/14/16 approx 1300, Email 1/14/15 1720</i>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

Had a fire in the heater treater due to gas in the FWKO. Heater treater has been repaired and returned to service.

Describe Area Affected and Cleanup Action Taken.*

Affected area was 3'x3' area around heater treater. Hydrocarbons were burned off. General housekeeping of area around HT and no further action required.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>Leslie Garvis</i>	Approved by Environmental Specialist: <i>[Signature]</i>	
Printed Name: <i>Leslie Garvis</i>	Approval Date: <i>1/21/16</i>	Expiration Date: <i>N/A</i>
Title: <i>Regulatory Coordinator</i>	Conditions of Approval: <i>FINAL</i>	
E-mail Address: <i>lgarvis@burnettoil.com</i>	Attached <input type="checkbox"/>	
Date: <i>1/21/16</i>	Phone: <i>817-583-8730</i>	

* Attach Additional Sheets If Necessary

289 3509

Patterson, Heather, EMNRD

From: Leslie Garvis <lgarvis@burnettoil.com>
Sent: Thursday, January 21, 2016 10:52 AM
To: stucker@blm.gov; Patterson, Heather, EMNRD
Cc: Walter Glasgow; Brady Sullivan; Trey Krampf; Belton Mathews; Kyle Adams; Johnny Titsworth
Subject: RE: Incident at the Jackson B 6 Battery / API# 30-015-31333
Attachments: 2012.01.21 JB 6 C-141.pdf

30-015-04326

Shelly/Heather,

Attached you will find our Initial & Final C-141 for the incident at the Jackson B 6 Tank Battery. The damage was minimal and has been cleaned up.

Please let me know if you have any questions or need any additional information.

Thank you,

LESLIE M. GARVIS
REGULATORY COORDINATOR

BURNETT OIL Co., INC.
BURNETT PLAZA-SUITE 1500
801 CHERRY STREET - UNIT #9
FORT WORTH, TX 76102-6881
DIRECT LINE: 817.583.8730
MOBILE: 713.819.4371
FAX: (817) 332-2438
EMAIL: LGARVIS@BURNETTOIL.COM

From: Leslie Garvis
Sent: Thursday, January 14, 2016 5:20 PM
To: stucker@blm.gov; Heather.Patterson@state.nm.us
Cc: Walter Glasgow; Brady Sullivan; Trey Krampf; Belton Mathews; Kyle Adams; Johnny Titsworth
Subject: Incident at the Jackson B 6 Battery / API# 30-015-31333

This API # is operated by Apache

Shelly/Heather,

To follow up on our earlier conversations, we had a small fire at the Jackson B 6 Battery on 1/13/16. We believe the incident was caused by gas in the FWKO which did not allow the heater treater to work properly. The fire covered a small area approximately 5'x5'. Our lease operators were in the field and quickly shut down the wells going to this location. The fire was quickly extinguished and no one was hurt.

Once I have further information, I will submit the C-141.

Thank you,

LESLIE M. GARVIS
REGULATORY COORDINATOR

BURNETT OIL Co., Inc.
BURNETT PLAZA-SUITE 1500
801 CHERRY STREET - UNIT #9
FORT WORTH, TX 76102-6881
DIRECT LINE: 817.583.8730
MOBILE: 713.819.4371
FAX: (817) 332-2438
EMAIL: LGARVIS@BURNETTOIL.COM

This message is intended only for the person(s) to which it is addressed and may contain privileged, confidential and/or insider information. If you have received this communication in error, please notify us immediately by replying to the message and deleting it from your computer. Any disclosure, copying, distribution, or the taking of any action concerning the contents of this message and any attachment(s) by anyone other than the named recipient(s) is strictly prohibited.