

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

MAR 01 2016

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1606239294 OPERATOR Initial Report Final Report

Name of Company: BOPCO, L.P. <i>2/10/16</i>	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: Poker Lake Unit 78 Tank Battery	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-27536
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	25	24S	30E	660		660		Eddy

Latitude: 32.194170 Longitude: 103.827430

NATURE OF RELEASE

Type of Release: Crude oil and produced water	Volume of Release: 65 barrels PW and 54 barrels Oil	Volume Recovered: 50 barrels oil and 50 barrels PW
Source of Release: Failed HT Gasket	Date and Hour of Occurrence: 2-27-16 @ 1:00pm	Date and Hour of Discovery: 2-27-16 @ 1:30pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, Heather Patterson and Jim Amos BLM	
By Whom? Bradley Blevins via email	Date and Hour: 2-27-16 @ 2:42pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

BOPCO EHS was notified of a release that occurred at the PLU 78 due to a failed heater treater gasket. A vacuum truck was called to the location to recover the fluid within the firewall.

Describe Area Affected and Cleanup Action Taken.*

The majority of the fluid was contained within the earth berm with the exception of a light overspray on the northern half of the location. A vacuum truck was called to the location and recovered 50 barrels of oil and 50 barrels of produced water from the firewall.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bradley Blevins</i>	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Bradley Blevins	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Assistant Remediation Foreman	Approval Date: 3/2/16	Expiration Date: N/A
E-mail Address: bblevins@basspet.com	Conditions of Approval: <input type="checkbox"/> Attached <input type="checkbox"/>	
Date: 3-1-16	Phone: 432-214-3704	

Remediation per O.C.D. Rules & Guidelines
SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 3/2/16

2RD-3576

* Attach Additional Sheets If Necessary

Patterson, Heather, EMNRD

From: Blevins, Bradley <BBlevins@BassPet.Com>
Sent: Tuesday, March 01, 2016 11:03 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; jamos@blm.gov
Cc: Blevins, Bradley
Subject: Initial C-141 PLU 78 HT 2-27-16
Attachments: Initial C-141 PLU 78 HT 2-27-16.pdf

All,

Please find the attached initial C-141 for the release that occurred at the PLU 78 battery, if you have any questions please let me know. Thanks

Brad Blevins
BOPCO, LP
522 W. Mermod, Suite 704
Carlsbad, NM 88220
Office-575-887-7329
Cell-1-432-214-3704
bblevins@basspet.com

Patterson, Heather, EMNRD

From: Blevins, Bradley <BBlevins@BassPet.Com>
Sent: Saturday, February 27, 2016 2:42 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Jim Amos
Cc: Blevins, Bradley
Subject: PLU 78 Battery

All,
This email is to inform you that BOPCO had a release on the PLU 78 due to a failed gasket on the Heater. A Vacuum truck has been called to the location to recover fluid from inside the firewall. I will follow up with an initial C-141 once I have all the details. If you have any questions please let me know. Thanks

Sent from my iPhone