

NM OIL CONSERVATION

ARTESTA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

APR 1 2016

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1609640449

OPERATOR

Initial Report Final Report

Name of Company: BOPCO, L.P. <i>260737</i>	Contact: Amy Ruth
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: Legg Federal 001	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-04734
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	27	22S	30E	660	North	2004	East	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Crude Oil	Volume of Release	46 bbls	Volume Recovered	40 bbls
Source of Release	LACT Unit Filter Pot Valve	Date and Hour of Occurrence	3/17/2016 8:42 am	Date and Hour of Discovery	3/17/2016 9:10 am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher/Heather Patterson (NMOCD), Jim Amos (BLM)		
By Whom?	Amy Ruth	Date and Hour	3/17/2016 2:14 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
LACT unit operated by Plains experienced a filter pot ball valve failure. The leak was detected by BOPCO on site security cameras and Plains personnel closed the leaking valve. The valve was replaced with a Balon valve and secured with a dart and seal.

Describe Area Affected and Cleanup Action Taken.*
The leak affected 4,436 square feet of caliche pad within the fenced facility. Standing fluids were recovered from the ground and from within the zero perm tank containment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: *[Handwritten Signature]*
Printed Name: Amy C. Ruth
Title: EHS Remediation Specialist
E-mail Address: ACRuth@basspet.com
Date: 4/1/2016 Phone: 432-661-0571

OIL CONSERVATION DIVISION
Approved by Environmental Specialist: *[Signature]*
Approval Date: *4/5/16* Expiration Date: *N/A*
Conditions of Approval:
Remediation per O.C.D. Rules & Guidelines
SUBMIT REMEDIATION PROPOSAL NO
Attached

* Attach Additional Sheets If Necessary

LATER THAN: 5/5/16 *2RD-3639*

Bratcher, Mike, EMNRD

From: Ruth, Amy C. <ACRuth@BassPet.Com>
Sent: Friday, April 01, 2016 2:57 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Jim Amos
Subject: RE: Legg Federal Battery release 3-17-16
Attachments: Initial C-141 Legg Federal Battery #1 3-17-16.pdf

Here is the initial form C-141 for this event. There has been much talk regarding this spill. It will be handled in short order, I believe... Thanks for your help, everyone...

From: Ruth, Amy C.
Sent: Thursday, March 17, 2016 2:14 PM
To: Mike Bratcher; EMNRD Patterson Heather
Cc: Jim Amos
Subject: Legg Federal Battery release 3-17-16

All, BOPCO had an accidental release of crude oil at the battery and a C-141 will be submitted with full details to follow this initial notification. Most of the fluids were released and currently being recovered from the containment. Some fluids were also released to the well pad within the fenced area. Please contact me with any questions. Thank you.

Sent from my iPhone

Begin forwarded message:

From: "Fuqua, D. Jace" <DJFuqua@BassPet.Com>
Date: March 17, 2016 at 1:59:29 PM MDT
To: "Cottle, Richard" <RCottle@BassPet.Com>, "Johnson, Steve F" <SJohnson@BassPet.Com>, "Hanna, Wesley W." <WWHanna@BassPet.Com>, "Ruth, Amy C." <ACRuth@BassPet.Com>, "Blevins, Bradley" <BBlevins@BassPet.Com>
Subject: Wellsite Share from Wellsite Navigator Pro iOS

The following Wellsite information and coordinates have been shared with you via Wellsite Navigator Pro iOS Edition.

Name: legg federal 001 bopco l.p.
Description: API: 3001504734
Latitude: 32.368583
Longitude: -103.866848

[See a Map of this Well](#)

For additional information regarding the Wellsite Navigator app check us out in the [Google Play Store](#) or in the [iTunes App Store](#)

Lease operator reported release at facility due to failed valve on on filter pot of lact unit. Down stream of valve there is a hose installed and open ended into impervious containment. This allowed lease operator to clear filter pot without draining oil onto the ground. The hose was not