

JUN 07 2016

Form C-141  
Revised August 8, 2011

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit Copy to appropriate District Office in  
Receivable with 19.15.29 NMAC.

**Release Notification and Corrective Action**

*NABILA0053915*

**OPERATOR**

Initial Report  Final Report

Name of Company: COG Operating LLC <i>229137</i>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: SRO SWD #103	Facility Type: SWD
Surface Owner: State	Mineral Owner: State
API No. 30-015-24462	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	17	26S	28E	660'	South	660'	West	Eddy

Latitude 32.0369301 Longitude -104.1160126

**NATURE OF RELEASE**

Type of Release: Oil	Volume of Release: 15 bbls oil	Volume Recovered: 13 bbls oil
Source of Release: Flowline	Date and Hour of Occurrence: 5/28/2016 unknown	Date and Hour of Discovery: 5/28/2016 12:00 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
This release was caused by a check valve failure on a flowline inside the containment. A vacuum truck was dispatched to recover the standing fluid inside the containment.

Describe Area Affected and Cleanup Action Taken.\*  
This release occurred within the lined containment. Concho will have the spill site inspected for any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Robert McNeill</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Robert McNeill	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Environmental Manager	Approval Date: <i>6/8/16</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>rmcneill@concho.com</i>	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/>	
Date: June 6, 2016	Phone: 432-230-0077	
<b>SUBMIT REMEDIATION PROPOSAL NO</b>		

\* Attach Additional Sheets If Necessary.

LATER THAN: *7/1/16* *ARD-3120*

## Bratcher, Mike, EMNRD

---

**From:** Robert McNeill <RMcNeill@concho.com>  
**Sent:** Tuesday, June 07, 2016 2:35 PM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Groves, Amber; Strang, Dana V.; Martin, Ed; Naranjo, Mark M.  
**Subject:** SRO SWD #103 - C141  
**Attachments:** 5-28-2016 SRO SWD #103 (TB) Initial.pdf

Mr. Bratcher/Ms. Groves,

COG Operating LLC is reporting a release on the SRO SWD #103 (30-015-24462)  
Unit M Section 17 Township 26S Range 28E  
The release occurred at 12:00 pm on 5/28/2016  
Released: 15 bbls oil  
Recovered: 13 bbls oil

This release was caused by a check valve failure on a flowline inside the containment. A vacuum truck was dispatched to recover the standing fluid inside the containment. This release occurred within the lined containment. Attached is a C-141 for your consideration. If you have any additional questions please feel free to contact me.

Thank you,

Robert McNeill, P. E.  
Environmental Manager  
COG Operating LLC

One Concho Center  
600 West Illinois Avenue  
Midland, TX 79701  
Office 432.221.0388  
Cell 432.638.6470

**CONFIDENTIALITY NOTICE:** The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

**CONFIDENTIALITY NOTICE:** The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.