

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

JUN 22 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1617548689 OPERATOR Initial Report Final Report

Name of Company	Oxy Permian Ltd. <u>166916</u>	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	Cedar Canyon 15 #1 SWD	Facility Type	SWD
Surface Owner	McDonald	Mineral Owner	API No. 30-015-42797

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
SW ¼	15	24S	29E					Eddy

Latitude N 32.21642° Longitude W 103.97952°

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	155 bbls	Volume Recovered	154 bbls
Source of Release	Power outage caused skim tank spill	Date and Hour of Occurrence	06/17/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Heather Patterson- NMOCD		
By Whom?	Kathy Purvis @ BBC International Inc.	Date and Hour	06/20/2016 @ 1:17 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
A power outage caused a skim tank to spill 155 bbls of oil. A vacuum truck recovered 154 bbls of oil and the power was restored.

Describe Area Affected and Cleanup Action Taken.*
The affected area is approximately 60' x 120' on location inside the lined containment. Remediation will be completed by removing the contaminated material and replacing it with clean material.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Casey Summers	Approved by Environmental Specialist:	
Title:	NM Environmental Advisor	Approval Date:	06/23/16
E-mail Address:	Casey_Summers@oxy.com	Expiration Date:	N/A
Date:	6-21-16	Phone:	(575) 513-8289
Conditions of Approval:		Attached <input type="checkbox"/>	
Remediation per O.C.D. Rules & Guidelines		SUBMIT REMEDIATION PROPOSAL NO	
LATER THAN:		7/27/16	

* Attach Additional Sheets If Necessary

2RD-5753

Patterson, Heather, EMNRD

From: Kathy Purvis <kathy@bbcinternational.com>
Sent: Tuesday, June 21, 2016 4:19 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Casey_Summers@oxy.com; dusty_wilson@oxy.com; jennifer_duarte@oxy.com; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; jgilkey@bbcinternational.com
Subject: Initial C-141, Cedar Canyon 15 #1 SWD
Attachments: Initial C-141, Cedar Canyon 15 #1 SWD.pdf

Attached is the initial C-141 for a leak that occurred at the Cedar Canyon 15 #1 SWD on 06/17/2016 in Eddy County, NM. Receipt notification via email is greatly appreciated.

Kathy Purvis

BBC International, Inc.
1324 W. Marland Blvd.
Hobbs, NM 88240
Business: (575) 397-6388
Cell: (575) 441-8619
kathy@bbcinternational.com

Patterson, Heather, EMNRD

From: Kathy Purvis <kathy@bbcinternational.com>
Sent: Monday, June 20, 2016 1:17 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; stucker@blm.gov
Cc: Casey_Summers@oxy.com; dusty_wilson@oxy.com; jennifer_duarte@oxy.com;
cbrunson@bbcinternational.com; kswinney@bbcinternational.com;
jgilkey@bbcinternational.com; kathy@bbcinternational.com
Subject: Cedar Canyon 15 #1 SWD

This is to inform you that Oxy Permian had a leak at the Cedar Canyon 15 #1 SWD on June 17, 2016. Oxy release 155 bbls of oil due to a power outage causing the skim tank to spill. A vacuum truck recovered 154 bbls of oil. The preliminary report states the spill is approximately 60' x 120' on location inside the lined berm. The release is location in the SW ¼ of Section 15, T24S, R29E in Eddy County, NM. Driving directions: Malaga – Intersection of Hwy 285 & Duarte Road, go east on Duarte Road for 1.5 miles to McDonald Road, turn right (S) on McDonald follow to end of pavement & cross river. After river is S-curve follow to 2nd cattle guard, turn left (W) at 2nd cattle guard for 0.2 mile to Oxy Gaines sign. Turn right (N), follow main road 0.8 mile to cattle guard, at cattle guard get off main road continue (north) straight, take road around 0.1 mile to 2nd left (N) take left (N) through Oxy locations. Stay on main road for 0.4 mile to a crossing, take right (E) road with an immediate left (N). Take left (N) 0.3 mile through Oxy locations to location. GPS coordinates: N 32.21642° W 103.97592° API# 30-015-42797

Kathy Purvis

BBC International, Inc.
1324 W. Marland Blvd.
Hobbs, NM 88240
Business: (575) 397-6388
Cell: (575) 441-8619
kathy@bbcinternational.com