

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**NM OIL CONSERVATION**

ARTESIA DISTRICT Form C-141  
Revised August 8, 2011

JUL 29 2016  
Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

**Release Notification and Corrective Action**

*NAB/621456328* OPERATOR  Initial Report  Final Report

Name of Company: BOPCO, L.P. <i>240737</i>	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU CVX JV PC 001H (AKA PLU PC 17)	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner:
API No. 30-015-36635	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	17	25S	30E	350		350		Eddy

Latitude: 32.123950 Longitude: 103.895943

**NATURE OF RELEASE**

Type of Release: Produced Water	Volume of Release: 9.5 barrels PW	Volume Recovered: None
Source of Release: Poly line failed	Date and Hour of Occurrence: 7-23-16 @ 8:00am	Date and Hour of Discovery: 7-23-16 @ 8:45am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Poly flowline was located to close to the flare, the heat from the flare caused poly line to rupture. Produced water was released to the well pad and surrounding soils. An initial response crew will be dispatched to the location to conduct a scrape and sampling event.		
Describe Area Affected and Cleanup Action Taken.* Poly line was repaired and relocated away from the flare. A vacuum truck was called to the location, by the time the driver arrived to recover the standing fluid had soaked in.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <i>Bradley Blevins</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Bradley Blevins	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Assistant Remediation Foreman	Approval Date: <i>8/1/16</i>	Expiration Date: <i>NIA</i>
E-mail Address: bblevins@basspet.com	Conditions of Approval: <b>Remediation per O.C.D. Rules &amp; Guidelines</b>	
Date: <i>7-29-16</i> Phone: 432-214-3704	Attached <input type="checkbox"/>	

**SUBMIT REMEDIATION PROPOSAL NO**  
**LATER THAN: *4/2/16* *2RP-3813***

\* Attach Additional Sheets If Necessary

**Patterson, Heather, EMNRD**

---

**From:** Blevins, Bradley <BBlevins@BassPet.Com>  
**Sent:** Thursday, July 28, 2016 10:17 AM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Tucker, Shelly (stucker@blm.gov)  
**Cc:** Blevins, Bradley  
**Subject:** Initial C-141 PLU CVX JV PC 001H  
**Attachments:** scan.pdf

All,

Please find the attached initial C-141 for the release that occurred at the PLU CVX JV PC 001H. A initial response crew will be dispatched to location to conduct an initial scrape and sampling event. Let me know if you have any questions. Thanks

Brad Blevins  
BOPCO, LP  
522 W. Mermod, Suite 704  
Carlsbad, NM 88220  
Office-575-887-7329  
Cell-1-432-214-3704  
bblevins@basspet.com