

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

AUG 12 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

DAB1102282727

OPERATOR

Initial Report Final Report

Name of Company: COG Operating LLC <i>229131</i>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: SHINER BOCK I FEDERAL COM #027H	Facility Type: Battery

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-42022
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	01	17S	31E	1160	South	170	West	Eddy

32.8595657,-103.8312531

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: 0.5 bbls Oil ; 4.5 bbls PW	Volume Recovered: 0 bbls Oil ; 3.5 bbls PW
Source of Release: Steel Flowline	Date and Hour of Occurrence: 8/4/2016 unknown	Date and Hour of Discovery: 8/4/2016 10:10 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

This release was caused by a corroded steel flowline at the well. Vacuum trucks were dispatched to recover standing fluids and the equipment was pressure washed.

Describe Area Affected and Cleanup Action Taken.*

The release remained on location around the wellhead. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Dakota Neel</i>	OIL CONSERVATION DIVISION	
Printed Name: Dakota Neel	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Environmental Coordinator	Approval Date: <i>8/15/16</i>	Expiration Date: <i>N/A</i>
E-mail Address: dneel2@concho.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: 8/12/2016 Phone: 432-215-2783	SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: *8/15/16*

ARP-3829

Patterson, Heather, EMNRD

From: Dakota Neel <DNeel2@concho.com>
Sent: Friday, August 12, 2016 4:08 PM
To: James_Amos@blm.gov; Patterson, Heather, EMNRD; stucker@blm.gov; Bratcher, Mike, EMNRD
Cc: Robert McNeill
Subject: (Notification/C-141 Initial) Shiner Bock 1 Federal Com #027H (30-015-42022)
Attachments: 8-4-2016 Shiner Bock 1 Federal Com #27H Initial.pdf

Ms. Patterson/Ms. Tucker,

COG Operating LLC is reporting a release on the Shiner Bock 1 Federal Com #027H.
Unit M Section 01 Township 17S Range 31E
The release occurred on 8/4/2016
Released: 0.5 bbls Oil; 4.5 bbls PW
Recovered: 0 bbls Oil; 3.5 bbls PW

This release was caused by a corroded steel flowline. A Vacuum truck was dispatched to recover all standing fluids. The release remained on location. Attached is a C-141. If you have any questions please feel free to contact me..

Thank you,

Dakota Neel
Environmental Coordinator
COG Operating LLC
Cell: 432-215-2783
dneel2@concho.com

2407 Pecos Ave.
Artesia , NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.