

Received 9/7/16
 NMOC
 Artesia

District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 811 S. First St., Artesia, NM 88210
 District III
 1000 Rio Brazos Road, Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy Minerals and Natural Resources
 Oil Conservation Division
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

Form C-14
 Revised August 8, 20

Submit 1 Copy to appropriate District Office
 accordance with 19.15.29 NMAI

FAB1626329823 Release Notification and Corrective Action

NAB1626330053 OPERATOR Initial Report Final Report

Name of Company DCP Midstream, LP 227828	Contact Yvonne Blair
Address 10 Desta Drive, Suite 400 West	Telephone No. 575-234-6404 cell 575-361-2406
Facility Name B-10 Gas Gathering Pipeline	Facility Type Natural Gas Gathering Pipeline
Surface Owner State of NM	Mineral Owner
API No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	13	19S	S28					Eddy

Latitude 32.66010065 Longitude -104.1296158

NATURE OF RELEASE

TBD @ final

Type of Release: Raw Natural Gas, Condensate	Volume of Release 5 bbl	Volume Recovered 0 bbl
Source of Release B-10 Gas Pipeline	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 9-1-2016
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.* N / A

Describe Cause of Problem and Remedial Action Taken.*
 DCP will excavate and repair the damaged sections and the excavations left open until remedial action can occur.

Describe Area Affected and Cleanup Action Taken.*
 A cleanup plan will be submitted for BLM and OCD Approval. The excavation from the repairs will be left open until remediation can be completed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Yvonne Blair	Approved by Environmental Specialist:	
Title: Compliance Coordinator	Approval Date: 9/15/16	Expiration Date: N/A
E-mail Address: ybblair@dcpmidstream.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO	Attached <input type="checkbox"/>
Date: 9-7-2016 Phone: 575-234-6404	LATER THAN: 10/20/16	

* Attach Additional Sheets If Necessary

2RD-3889

Patterson, Heather, EMNRD

From: Blair, Yvonne B <YBBlair@dcpmidstream.com>
Sent: Wednesday, September 07, 2016 12:00 PM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD
Cc: Rhoades, Alexandra M; Conder, Haskell P; Hanna, Jennifer; Cook, John W
Subject: B-10 Initial C141 Line Leak
Attachments: B-10 C141 initial line leak.pdf; B-10 Cleanup Plan (2).docx

Heather Patterson,

Attached is the C141 and cleanup plan for the line leak on DCP B-10 line located in Eddy County. DCP was notified of a line leak on the State Well by BLM Representative Shelly Tucker on 09-1-16.

DCP construction will evaluate pipeline and make associated repairs. I will notify you when site is available for sampling and coordinate site visit.

If you have any questions or concerns please contact me.

Thanks,

Yvonne Blair
Compliance Coordinator
DCP Midstream
575-361-2406