

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1628542275 OPERATOR Initial Report Final Report

| | |
|--|---|
| Name of Company: BOPCO, L.P. <i>2100737</i> | Contact: Bradley Blevins |
| Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220 | Telephone No. 575-887-7329 |
| Facility Name: PLU 347 | Facility Type: Exploration and Production |
| Surface Owner: Federal | Mineral Owner: Federal |
| API No. 30-015-38668 | |

LOCATION OF RELEASE

| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| C | 11 | 25S | 30E | 540 | | 1440 | | Eddy |

Latitude: 32.150845 Longitude: 103.855589

NATURE OF RELEASE

| | | |
|--|--|--|
| Type of Release: Produced Water | Volume of Release: 273 barrels | Volume Recovered: 230 barrels |
| Source of Release: Failed connection on wellhead | Date and Hour of Occurrence: 10-07-16 @ 11:00am | Date and Hour of Discovery: 10-07-16 @ 12:30pm |
| Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? Mike Bratcher, Heather Patterson, Jim Amos BLM via email | |
| By Whom? Bradley Blevins | Date and Hour: 10-7-16 @ 3:43pm | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The lease operator arrived on location and found the release was caused by corrosion on the nipple that connects the tubing gauge to the Baird BPV, the nipple broke off causing the release. Vacuum trucks were called to the location and were able to recover 230 barrels of fluid from the location. All fluid remained on the well pad.

Describe Area Affected and Cleanup Action Taken.*

A initial response crew was dispatched to the location and began removing the saturated surface soils and stockpiled soil on plastic until the material can be hauled to a disposal facility. The release area was also sampled once the saturated surface soils were removed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | | |
|---|--|--|-----------------------------|
| Signature: <i>Bradley Blevins</i> | | OIL CONSERVATION DIVISION | |
| Printed Name: Bradley Blevins | | Approved by Environmental Specialist: <i>[Signature]</i> | |
| Title: Assistant Remediation Foreman | | Approval Date: <i>10/11/16</i> | Expiration Date: <i>NIA</i> |
| E-mail Address: bblevins@basspet.com | | Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> | |
| Date: <i>10-10-16</i> Phone: 432-214-3704 | | SUBMIT REMEDIATION PROPOSAL NO | |

* Attach Additional Sheets If Necessary

LATER THAN: *11/2/16*

ARP-3931

Patterson, Heather, EMNRD

From: Blevins, Bradley <BBlevins@BassPet.Com>
Sent: Monday, October 10, 2016 2:46 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; jamos@blm.gov
Cc: Blevins, Bradley
Subject: Initial C-141 PLU 347
Attachments: scan.pdf

All,

Please find the initial C-141 for the release that occurred at the PLU 347. If you have any questions please let me know. Thanks

Brad Blevins
BOPCO, LP
522 W. Mermod, Suite 704
Carlsbad, NM 88220
Office-575-887-7329
Cell-1-432-214-3704
bblevins@basspet.com

Patterson, Heather, EMNRD

From: Blevins, Bradley <BBlevins@BassPet.Com>
Sent: Friday, October 07, 2016 3:43 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Jim Amos; Blevins, Bradley
Subject: PLU 347

BOPCO EHS was notified of a reportable spill on location due to a failed nipple and valve on the wellhead. We have a vacuum truck on location as well as an initial scrape response crew. I will follow up with a initial C-141 ASAP. If you have any questions please let me know. Thanks

Sent from my iPhone