

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1630540429

OPERATOR Initial Report Final Report

Name of Company: COG Operating LLC <i>229137</i>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: ADMIRAL FEDERAL COM #002H	Facility Type: Battery

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015- 42480
------------------------	------------------------	----------------------------------

LOCATION OF RELEASE

47820

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	28	25S	29E	190	South	1980	East	Eddy

32.0940460962434, -103.9871068537

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 355 bbls of Oil	Volume Recovered: 350 bbls of Oil
Source of Release: Valve	Date and Hour of Occurrence: 10/18/2016 7:00 AM	Date and Hour of Discovery: 10/18/2016 8:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher NMOCD/ Shelly Tucker BLM	
By Whom? Dakota Neel	Date and Hour: 10/20/2016 1:49 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
The release was caused by an equalizer valve being in the wrong position. The valve was placed back in the correct position. Vacuum trucks were immediately dispatched to recover all standing fluids.

Describe Area Affected and Cleanup Action Taken.*
This release was contained within the falcon lined facility. Free standing fluids were removed via vacuum truck and the facility was pressure washed. Concho will have the spill site inspected for any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Dakota Neel</i>	OIL CONSERVATION DIVISION	
	Approved by Environmental Specialist:	
Printed Name: Dakota Neel	Approval Date:	Expiration Date:
Title: Environmental Coordinator	Conditions of Approval:	
E-mail Address: dneel2@concho.com	Attached <input type="checkbox"/>	
Date: October 25, 2016	Phone: 575-748-6933	

* Attach Additional Sheets If Necessary

2RP-3962